



Oblique readout optical setup




wrong configuration

The polarization of the laser beam should be rotated 90 degrees and the horizontal polarization should be used.



Correct configuration



The linear polarization of the incident beam is changed to the elliptic one.