

PEST AND WOOD-DESTROYING ORGANISM REPORT

Transaction 48291 · v1 · Page 1 of 2

1

ORDER AND SCOPE

Fictional operator Harborfield Timber Review; work order WDO-48291; 123 Main Street, Harborfield; ordered by Taylor Morgan. Visit August 25, 2026. Inspection type: accessible-area visual; no destructive opening. Diagram key: A front entry, B garage, C rear planter, D attic hatch. Inspector Casey Bell, invented registration DEMO-WDO-08. No actual state-issued clearance is represented.

2

NUMBERED FINDINGS

1A	Entry trim	No visible active wood-destroying infestation in
1B	Garage sill	Accessible portion visually examined; west stora
2A	Rear planter	Maintain separation of soil and wood edging; pre
3A	Concealed wall interiors	Not accessed; no finding about concealed organis
4A	Treatment recommendation	No open treatment or clearance requirement recor

examined areas.

3

CONDITIONS AT VISIT

Access was arranged through the listing representative for the morning appointment. The residence was occupied, furnished, and served by operating water and electricity. Storage along the west garage wall prevented examination of the lower portion of that wall. Furniture and personal effects were not moved. Weather was dry following several days without measurable rain; an absence of active leakage under those conditions does not establish performance during a storm. Photographs referenced by observation number identify the location of a visible condition and are not a comprehensive photographic inventory. Detached furnishings and personal appliances were outside the assignment.

4

COMPLETION AND EXCLUSIONS

No pesticide application, drilling, fumigation, structural repair, or clearance reinspection was performed under this order. A maintenance suggestion is not a treatment certificate. If stored items are moved, an additional inspection can address the newly accessible area. Any later bid shall list the numbered finding it covers and identify whether concealed damage discovered during work changes its scope. Owner receipt does not adopt an opinion about excluded wall interiors.

5

METHODS AND INACCESSIBLE AREAS

Observations were made from normally accessible floors, exterior grade, and the attic hatch where safe. No finish was removed and no destructive test was performed. A readily accessible switch or faucet was operated once; equipment was not dismantled or subjected to a prolonged load test. The inspector did not survey property lines, measure structural

PEST AND WOOD-DESTROYING ORGANISM REPORT

Transaction 48291 · v1 · Page 2 of 2

1

METHODS AND INACCESSIBLE AREAS — CONTINUED

capacity, verify an underground pipe route, or determine code compliance. An item described as serviceable means that the limited operation described was observed, not that its remaining service life was determined. A specialist's evaluation may use additional instruments or access not available during this visit.

2

FOLLOW-UP REGISTER

Keep a repair invoice with the observation number to which it relates, the contractor's scope, and the completion date. An invoice for a single component does not close unrelated observations in the same room. Where a component was inaccessible, later access should be documented before anyone treats that component as examined. Any repair request transmitted by the buyer is separate from this report and requires the parties' written agreement to change the transaction. Reinspection, if ordered, is limited to the stated repaired items and should not be described as a new inspection of the whole property. These observations are not an authorization to enter after possession has transferred.

3

INSPECTOR / RECIPIENT ACKNOWLEDGMENTS

Prepared/issued: /s/ Casey Bell — simulated electronic record, August 28, 2026 10:00.

Electronic copy certified complete by the fictional preparer; not a public-official certification or authorization to close.