

AGENT VISUAL INSPECTION DISCLOSURE

Transaction 48292 · v1 · Page 1 of 2

1 VISIT PARTICULARS

Subject 77 Juniper Lane, Harborfield. Avery Chen accompanied Rowan Price for an accessible-area visual walk on August 24, 2026, 10:15–10:55. Clear weather; electricity and water on; seller belongings present. This is the agents' observation record, not a licensed specialist's test report. The agent observations below refer only to readily observable conditions at the visit.

2 ROOM-BY-ROOM ENTRIES

Entry/hall: small scuff at lower east wall; no open floor covering seam observed. Living room: patch in painted ceiling near former light position, origin not established. Kitchen: faucet operated; cabinet base dry at visit. Rear bedroom: discoloration at lower window trim, seller refers to resealing receipt R-04. Hall bath: worn sealant at tub edge. Garage: boxes restricted view of west wall. Exterior: rear planter showed soil settlement adjacent to edging.

3 CONDITIONS AT VISIT

Access was arranged through the listing representative for the morning appointment. The residence was occupied, furnished, and served by operating water and electricity. Storage along the west garage wall prevented examination of the lower portion of that wall. Furniture and personal effects were not moved. Weather was dry following several days without measurable rain; an absence of active leakage under those conditions does not establish performance during a storm. Photographs referenced by observation number identify the location of a visible condition and are not a comprehensive photographic inventory. Detached furnishings and personal appliances were outside the assignment.

4 COMMUNICATION ENTRY

Observations transmitted to buyer August 24 with seller disclosure and the separate inspection reference. No request to open the rear bedroom wall was made during this visit. The agent has not determined whether the discoloration represents current moisture. Buyer may consult the home inspector about the location and the limits of the seller's repair receipt. No agent statement here certifies the roof, electrical system, sewer lateral, or structural adequacy.

5 METHODS AND INACCESSIBLE AREAS

Observations were made from normally accessible floors, exterior grade, and the attic hatch where safe. No finish was removed and no destructive test was performed. A readily accessible switch or faucet was operated once; equipment was not dismantled or subjected to a prolonged load test. The inspector did not survey property lines, measure structural

AGENT VISUAL INSPECTION DISCLOSURE

Transaction 48292 · v1 · Page 2 of 2

1

METHODS AND INACCESSIBLE AREAS — CONTINUED

capacity, verify an underground pipe route, or determine code compliance. An item described as serviceable means that the limited operation described was observed, not that its remaining service life was determined. A specialist's evaluation may use additional instruments or access not available during this visit.

2

FOLLOW-UP REGISTER

Keep a repair invoice with the observation number to which it relates, the contractor's scope, and the completion date. An invoice for a single component does not close unrelated observations in the same room. Where a component was inaccessible, later access should be documented before anyone treats that component as examined. Any repair request transmitted by the buyer is separate from this report and requires the parties' written agreement to change the transaction. Reinspection, if ordered, is limited to the stated repaired items and should not be described as a new inspection of the whole property. These observations are not an authorization to enter after possession has transferred.

3

INSPECTOR / RECIPIENT ACKNOWLEDGMENTS

Prepared/issued: /s/ Avery Chen and Rowan Price — simulated electronic record, August 28, 2026 10:00.

Electronic copy certified complete by the fictional preparer; not a public-official certification or authorization to close.