

Carrier calibration: RMS mismatch 0.174; residual dephasing 0.00068/s

