

REPORT CORRECTIVE ACTIONS

ID: 8D090621-1

Front seat cover with exposed fibers.

Product/Process Information:

2021 Chrysler Pacifica Pinnacle.

Date Opened:

2021-08-30

Last Update:

2021-09-06

Due Date:

2021-09-10

Reported By:

FRANCISCOE

D0 Symptom(s):

Front seat cushion cover with exposed fibers.

Action

* Involve all personnel in order to prevent defective material escape.

% Completed

50

D1 Team (Name, Dept, Phone):

Role	Name	Last Name	Mail	Department
TEAM MEMBERS	FRANCISCO	ESTEBAN	FRANCISCOE@PEARLLEATHER.COM.MX	SISTEMAS
TEAM LEADER	ALEJANDRO	DE LA ROSA	ALEJANDROD@PEARLLEATHER.COM.MX	SISTEMAS
CHAMPION	RAFAEL	FIERRO	RAFAELF@PEARLLEATHER.COM.MX	SISTEMAS

D2 Problem:

2021 Chrysler Pacifica Pinnacle front seat cushion cover with exposed fibers.

D3 Interim Containment Action(s):

Action

* Quality alert posted at all QC inspection station.

% Completed

60

* QC personnel meeting in order to inform about the issue.

70

D4 Root Cause(s):

	Cause	% Contribution
Occurrence	Production operator did not pass the leather pattern thru shaving process.	50
Detection	Only 1 of every 30 pieces pass thru air flow fibers detection process.	50

D5 Chosen Permanent Corrective Action(s):

Action

* Production operator will measure 1 / 5 shaved of the shaved material in order to find defective pieces.

% Completed

45

* QC inspector will pass 1 of each pack of 30 pieces thru air flow fiber detection process (before this quality complaint 1 piece per box passed thru air flow fiber detection).

65

D6 Prevention of occurrence for similar processes or products:

Description:

All RU shaved products will be inspected in the same way.

Similar processes or products:

All RU shaved products.

D7 Systemic Prevent Recommendations / Learned Lessons:

Recommendation:

Work instructions will be updated (6/18/2021).

Learned Lesson:

Shaving operation and inspection must be constantly improved.

D8 Team and Individual Recognition:

Gracias Equipo!

Date Closed: 2021-09-06