

MANGALORE REFINERY AND PETROCHEMICALS LIMITED

SCANNED NDT ULTRASONIC INSPECTION REPORT - CDU-1

INSPECTION DATE: 2026-09-15

EQUIPMENT IDENTIFIER: EX-402A

EQUIPMENT NAME: Crude Pre-Heat Exchanger Shell

MEASURED WALL THICKNESS: 3.10 mm

ALLOWABLE MINIMUM LIMIT (T-MIN): 4.50 mm

DEFECT FINDING: Severe localized pitting corrosion detected near nozzle N2.

STATUS: CRITICAL SAFETY HAZARD

RECOMMENDED ACTION:

Immediate unit isolation & shell weld overlay per MRPL SOP-MNT-2024-04.