

Lumo OLV data produce by Bad Lumo Injector causing OQ execution time out during Instrument Priming

Suspect that there might be obstruction in the Lumo Injector, Detect2, where the process control light/signal passes through. Calibration of Lumo OLV board was performed several times but still getting the same result. Replacing the Lumo injector fixed the issue.

