

●PMRS STEP 3 : RECURRENCE PREVENTION

AIM : DEVELOP HUMAN SKILL
TO ANALYZE ROOT CAUSE

Prepared by
Shift

DATE

HAPPEN

01.12.2025

ROOT CAUSE ANALYSIS (RCA)

AREA / LINE

DAC

M/C No.

Procrrs

BEARING

FREQUENCY

1

2

3

4

5

6

PROBLEM

X AXIS OVER LOAD

BREARDOWN DATE

1-DES-25

IMMEDIATE ACTION/CM

EST

*Repeat case criteria

4

1

YOKOTEN

ROOT CAUSE

YR

PC

3

2

KEEP ZERO

CMEASURE

ROOT CAUSE ANALYSIS / ANALISIS PUNCA MASALAH

Equipment Lifecurve

Capability/Design
Workload
Circumtance

Initial

Stable

Expiry Life

Wear Out

Abnormal Breakdown

Normal Breakdown

Roote cause

การออกแบบ
Design

การติดตั้ง (Installation) /
การ Operate

การซ่อมบำรุง
Maintenance

อายุการใช้งาน
Deterioration

X AXIS ALARM 51

MOTOR SERVO OVER LOAD

RESISTEN MOTOR SERVO
TIDAK STABIL,MOTOR SERVO
LEMBAB/BASAH

COVER KURANG RAPAT

R

ROOT CAUSE / PUNCA
MASALAH :

T/DATE

PIC

STATUS

C

LONG TERM C'MEASURE /
[REPLACE / KAIZEN / MODIFY]

MOTOR SERVO OVERLOAD

12/Jan/25

WINDRA

O

P

REFLETION [Skill / Review PM]

KASIH SILIKON PADA BAGIAN COVER DAN KENCANGKAN BOLT

12/Jan/25

ISTU

O

Y
O
K
O
T
E
N

ESSENCE KEY POINT

YOKOTEN POINT (PRIORITY AREA)

T/DATE

PIC

STATUS

Legend:

X

Not related

O

Applicable

ATTENDEES / READ BY

MANAGEMENT COMMENT (EDUCATION)

Dokument No

FR-MTC-GNP-059-00

Revisi No

00

Date

11-Dec-25

Item Revisi

-