

Undocking
Transit
Inspection
Homing
Docking
(a)
Urgency
Urgency (max 0.54)
Threshold 0.65
1.00
0.75
0.50
0.25
0.00
(b)
P(TakeoverRequest)
No takeover
Increased attention
Takeover requested
(c) evidence
nominal
degraded
worst state
not entered
SonarRange
Altitude
DVLStatus
USBLStrength
CameraQuality
ArUcoVisibility
Speed
Current
WaypointTrackingError
RangeToTarget
BatteryLevel
Fatigue
Stress
(d)
Operator
Fatigue
Stress
1.0
0.5
0.0
0
100
200
300
400
500
600
700
Mission time [s]