

Lloyd's Register Marine Surveyors (Singapore)

Independent Marine Cargo Survey — Case file #LR-SIN-2026-04-V552-A

Re-survey at destination: Hanseatic Marine Survey (Hamburg) • surveyor of record: Mr. Karthikeyan

MARINE CARGO DAMAGE SURVEY REPORT

Container	OCEAN-2026-04-V552 (40HQ)
Vessel / voyage	MV PIONEER WAVE / PW-PVG-HAM-2026-V04
Loading port	Shanghai (CNSHA)
Discharge port	Hamburg (DEHAM)
Incident location	Malacca Strait
Incident date	2026-04-12

1. Incident summary

Container door seal failed during a Force 8 squall in Malacca Strait. Saltwater ingress wet the back-bottom section of the container before the seal was re-secured at the next port of call. Wet stains and salt deposits are visible on the back wall and lower side panels. Survey conducted by Lloyd's-appointed surveyor Mr. Karthikeyan on 2026-04-15 at Singapore (transhipment) and re-surveyed at Hamburg 2026-05-08 by Hanseatic Marine Survey.

2. Cause classification — finding of fact

Cause classification: ordinary_water_damage_in_transit
Carrier negligence finding: no_gross_negligence_determined

The proximate cause is recorded as ordinary water damage in transit arising from a container door-seal failure during heavy weather. On the evidence available the surveyors did **not** find gross negligence on the part of the carrier or master. This finding is a finding of fact for the present record; it does not by itself determine coverage, which is governed by each cargo owner's own policy wording.

3. Damage-percentage methodology

carton_damage_pct: 0.0 = dry, 0.30 = roughly 30% of carton contents water-damaged (typically surface salt staining, some inner-product moisture exposure; commodity-dependent salvage value), 1.00 = full water damage (carton soaked through, contents unsalvageable).

4. Per-carton findings

Carton	Customer	Damage %	Surveyor note
L01	LINNEA	100%	Soaked, teak panels delaminated
L02	LINNEA	100%	Soaked, teak panels delaminated
L03	LINNEA	100%	Soaked, teak panels delaminated
L04	LINNEA	100%	Soaked, teak panels delaminated
L05	LINNEA	30%	Outer carton wet, table surface staining
L06	LINNEA	30%	Outer carton wet, table surface staining
L07	LINNEA	30%	Outer carton wet, table surface staining
L08	LINNEA	30%	Outer carton wet, table surface staining
L09	LINNEA	30%	Outer carton wet, table surface staining
L10	LINNEA	30%	Outer carton wet, table surface staining
L11	LINNEA	30%	Outer carton wet, table surface staining
L12	LINNEA	30%	Outer carton wet, table surface staining
J01	JONAS	0%	Dry — top tier front

Carton	Customer	Damage %	Surveyor note
J02	JONAS	0%	Dry — top tier front
J03	JONAS	0%	Dry — top tier front
J04	JONAS	0%	Dry — top tier front
J05	JONAS	0%	Dry — top tier front
J06	JONAS	0%	Dry — top tier front
J07	JONAS	0%	Dry — top tier front
J08	JONAS	0%	Dry — top tier front
M01	MAHMOUD	100%	Soaked, garments stained with salt water, mildew likely on natural fibres
M02	MAHMOUD	100%	Soaked, garments stained with salt water, mildew likely on natural fibres
M03	MAHMOUD	100%	Soaked, garments stained with salt water, mildew likely on natural fibres
M04	MAHMOUD	100%	Soaked, garments stained with salt water, mildew likely on natural fibres
M05	MAHMOUD	100%	Soaked, garments stained with salt water, mildew likely on natural fibres
M06	MAHMOUD	100%	Soaked, garments stained with salt water, mildew likely on natural fibres
M07	MAHMOUD	30%	Outer carton damp, top-layer garments moisture-affected
M08	MAHMOUD	30%	Outer carton damp, top-layer garments moisture-affected
M09	MAHMOUD	30%	Outer carton damp, top-layer garments moisture-affected
M10	MAHMOUD	30%	Outer carton damp, top-layer garments moisture-affected
M11	MAHMOUD	30%	Outer carton damp, top-layer garments moisture-affected
M12	MAHMOUD	30%	Outer carton damp, top-layer garments moisture-affected
M13	MAHMOUD	30%	Outer carton damp, top-layer garments moisture-affected
M14	MAHMOUD	30%	Outer carton damp, top-layer garments moisture-affected
M15	MAHMOUD	30%	Outer carton damp, top-layer garments moisture-affected
O01	OCEANTECH	30%	Outer carton damp, some surface salt deposits on fittings (cleanable)
O02	OCEANTECH	30%	Outer carton damp, some surface salt deposits on fittings (cleanable)
O03	OCEANTECH	30%	Outer carton damp, some surface salt deposits on fittings (cleanable)
O04	OCEANTECH	30%	Outer carton damp, some surface salt deposits on fittings (cleanable)
O05	OCEANTECH	30%	Outer carton damp, some surface salt deposits on fittings (cleanable)
O06	OCEANTECH	30%	Outer carton damp, some surface salt deposits on fittings (cleanable)
V01	VERDE	100%	Soaked, LED units short-circuited and salvage-impossible
V02	VERDE	100%	Soaked, LED units short-circuited and salvage-impossible
V03	VERDE	100%	Soaked, LED units short-circuited and salvage-impossible
V04	VERDE	30%	Outer carton damp, units functional but rated salt-tolerance reduced
V05	VERDE	30%	Outer carton damp, units functional but rated salt-tolerance reduced
V06	VERDE	30%	Outer carton damp, units functional but rated salt-tolerance reduced
V07	VERDE	30%	Outer carton damp, units functional but rated salt-tolerance reduced
V08	VERDE	30%	Outer carton damp, units functional but rated salt-tolerance reduced
V09	VERDE	30%	Outer carton damp, units functional but rated salt-tolerance reduced

5. Statement

The damage percentages above represent the surveyors' considered estimate of the proportion of each carton's contents affected by water ingress, after joint inspection at Singapore (transshipment) and re-inspection at Hamburg. Both surveys concur on the figures stated. This report is issued for the cargo interests and their insurers without prejudice.