
version material 200507005876 A0



Technical requirements:

- 1. Pay attention to closing both ends of the braided sleeve to prevent it from opening up. 2. Wrap the black acetic acid tape tightly and make sure the edges do not come apart. 3. The terminal clamp should be tightly crimped and cannot fall out.

6

5

| 1 | seria | _ | | 2 | ω | 4 | |
|----------|--|---|-------------------------------|-------------|--------|---|--|
| | a <mark>des</mark> c | WIFE | | | | | |
| | seria description | | | | | | |
| | ⊃ | | | | | | |
| | model | | | | | | |
| | | 1007 2 | | | | | |
| | | 1007 24AWG black | | | | | |
| | black | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | ٩ | | | | | | |
| | quantity | | | | | | |
| | <u>/</u> \ | approve | check | design | - - | | |
| | a total | Φ | | LIU Ye | : | | |
| + For | total ōlfe ne | | | 2022. 12. 9 | | | |
| | | phas | Shenzhen jiexinhua technology | | | | |
| | | e marke | N+1 | zhen iie | | | |
| | _ | g ruantity | 2 | xinhııa | | | |
| | | weight | | technol | | | |
| | | proport | | | | | |
| | nambe | i dn awin | model | material | - | | |
| 100000 | flament runout sen | phase markenantityweight proportidnawingxHSV06P-08024-g | model JXHSV06P | <u>"</u> | - | | |
| board) | namber filament runout sensor (connect the mathematical) | -08024-g | 06P | | | | |
| l | connec | | <u> </u> | | | | |

first

number