

AI VEHICLE DEFECT INSPECTION


INSPECTION ID: #RPT-9999

COMMERCIAL DAMAGE ASSESSMENT REPORT

Generated: 2026-07-17 19:02:39

Vehicle Profile:	Tesla Model Y	Digital Health Score:	100/100 (Excellent)
License Plate:	TEST-AI-99	OBD Diagnostics:	No Faults
Vehicle Age:	2 Years	Overall Severity:	Medium
EV Battery Health:	96%	Total Defects Found:	2
Tire Condition:	Good	Estimated Repair Cost:	\$1,250.00

Visual Defect Analysis



Damage Assessment Details

Defect / Damage Type	Affected Part	Severity	Confidence	Estimated Repair Cost Range
Paint Damage	Side Panel	Moderate	82.5%	\$350 - \$750
Dent	Side Panel	Moderate	73.6%	\$400 - \$800

System Repair Recommendations

Based on our AI model inspection, we recommend the following repair procedures:

- **Paint Damage (Side Panel):** Sanding and multi-coat respraying of affected panels.
- **Dent (Side Panel):** Paintless Dent Repair (PDR) or panel reshaping needed.