

AI VEHICLE DEFECT INSPECTION

INSPECTION ID: #RPT-0001

COMMERCIAL DAMAGE ASSESSMENT REPORT

Generated: 2026-07-17 15:39:01

Vehicle Profile:	Tesla Model Y	Digital Health Score:	65/100 (Needs Maintenance)
License Plate:	string	OBD Diagnostics:	P0171: Fuel Trim System Lean
Vehicle Age:	7 Years	Overall Severity:	Minor
EV Battery Health:	88%	Total Defects Found:	4
Tire Condition:	Fair	Estimated Repair Cost:	\$635.00

Visual Defect Analysis



Damage Assessment Details

Defect / Damage Type	Affected Part	Severity	Confidence	Estimated Repair Cost Range
Broken Headlight	Light	Minor	77.2%	\$80 - \$180

Windshield Crack	Windshield	Minor	80.4%	\$100 - \$200
Broken Headlight	Light	Minor	76.3%	\$80 - \$180
Paint Damage	Hood	Minor	80.3%	\$150 - \$300

System Repair Recommendations

Based on our AI model inspection, we recommend the following repair procedures:

- **Broken Headlight (Light):** Lens cover replacement or complete headlight assembly replacement.
- **Windshield Crack (Windshield):** Resin injection for minor cracks; complete windshield replacement for major cracks.
- **Paint Damage (Hood):** Sanding and multi-coat respraying of affected panels.