SOURCE_ID: CCL-SOP-HEMM-01

TITLE: Standard Operating Procedure for Dumper Operations in Open Cast Mines

SOURCE_TYPE: Standard Operating Procedure

PAGE_COUNT: 4

PUBLICATION_DATE: 2023-05-10

SYNTHETIC: true

ISSUING_AUTHORITY: Central Coalfields Limited (CCL)

---

1. Objective: Standardize safe dumper operation procedures.

2. Pre-operation checks:

   - Check engine oil, coolant, and transmission fluid levels.

   - Ensure tires are properly inflated and have no visible damage.

   - Verify that the reverse alarm and camera are functioning.

3. Loading:

   - Wait for the excavator operator's signal before approaching.

   - Do not overload the dumper.

4. Dumping:

   - Approach the dump edge perpendicularly.

   - Maintain a distance of at least 3 meters from the crest.

   - Wait for the spotter's signal to dump.

5. Emergency: In case of brake failure, steer the dumper towards the runaway ramp or a pile of loose material.