



INVOICE

GST 820980373RT0001

C & S Heating and Cooling
10705 Chemainus Rd
Ladysmith, British Columbia V9G2A6
Canada

Mobile: 250-709-8302
www.cnsheating.com

BILL TO

Wayne

keith.cnsheating@gmail.com

Invoice Number: 800730

P.O./S.O. Number: 2 head daikin

Invoice Date: July 21, 2025

Payment Due: July 21, 2025

Amount Due (CAD): \$8,505.00

Product	Quantity	Price	Amount
Daikin 2MX18AXVJU 2 Port Ductless system 1.5 TON, 2-ZONE SYSTEMS 17 SEER2 / 9 HSPF2 / 10 EER2 VARIABLE-SPEED, INVERTER, COMPRESSOR 2 heads installed in common living Areas. Living room and bedroom Existing heat is baseboard. AHRI#207216088 Outdoor unit 2MX18AXVJU Indoor unit 1 CTX12AXVJU Indoor unit 2 CTX12AXVJU 15amp circuit required Fully installed backed by Daikins 10 year parts warranty. 1 year labour warranty Coverage may require backup heat in coldest temperaturesi	1	\$6,500.00	\$6,500.00
Panasonic Ventilation Upgrade Primary Ventilation Fan Replacement. Replacement of primary bathroom fan with Panasonic FV-0510VS1 Vented to outside of building. New fully insulated ducting as needed. Electrical Included and supplied by MOKO Electric.	1	\$1,600.00	\$1,600.00



INVOICE

GST 820980373RT0001

C & S Heating and Cooling
10705 Chemainus Rd
Ladysmith, British Columbia V9G2A6
Canada

Mobile: 250-709-8302
www.cnsheating.com

Product	Quantity	Price	Amount
Note Esp rebate # ESP1-Electricdf5d2db6 \$5000 towards heat pump \$1520 towards vent upgrade (\$1600@95%)	1	\$0.00	\$0.00

Subtotal: \$8,100.00

Gst 5%: \$405.00

Total: \$8,505.00
ESP1-Electriccdf5db6 Heat Pump -\$5000.00
ESP1-Electriccdf5db6 Ventilation -\$1520.00
Amount Due (CAD): \$1985.00
Bank Payment July 17th 2025 -\$1985.00
0.00

Notes / Terms

Please note: Prices do not reflect any applicable tariffs.

We accept Cash, Check and most major credit cards. Our preferred method E-Transfer. Please send E-Transfers to cnsheating@gmail.com Thank you for your business!

(Credit cards subject to a 3% processing fee)

Please note electrical install and upgrades not included unless specified. Also some drywall may need to be removed to accommodate fishing of thermostat wires and refrigerant piping. Repair of drywall not included if necessary. E&O accepted.