SECRET

UK EYES B'

UNCLASS

2000 · Position 45 31.3 S 53 34.5W

2007 C/D PD for reruns of COR 285

Weather Wind 25 knots from 270

Seastate 4 from 260

Cloud 50%

Vis 6NM

SSS 6+

SVP 020 - 4907

130 - 4907

200 - 4860

2015 Sunset

2135 CO COMMENT

Intend remaining at PD until I have decoded COR 287 - another grouper and then going deep to give the RS and his team a break!

2217 C/D 260

2359 CO DAILY SUMMARY

A quiet day.

SATURDAY 15 MAY 1982

0148 C/D PD Routine and fix

No new traffic

0225 C/D 260

0315 SINS Alarm

CO COMMENT

Brief loss of supplies to SINS caused a 50 knot EW speed error that necessitated a sea restart. I shall have to obtain 4 hourly fixes (ideally) for the next 48 hours to enable SINS corrections to be computed.

0725 C/D PD Routine, fix and ventilate

0735 Start ventilating

0800 Position 45 27.2S 54 10W

Weather Wind 30 knots from 270

Seastate 6 from 270

Cloud 60%

Vis 4 NM

SSS 6

SVP 020 4899 260 4895

0840 Stop ventilating

Traffic received COR 288, 289, 290, 291

SEGNIT

LINGLASSAIPM

B - 255/105 T - 24. Diesel signature 11.5hz spacing C/C 140 to resolve bearing

1003 B - 255 T - 24

CO COMMENT

This spacing could fit Guppy or S209 and the signature appeared suddenly. Intend altering course to obtain a FCS and close range.

1048 Sunrise

1110 C/C 180 to steady bearing rate of T - 24

1135 T - 24 faded during the C/C and not regained

CO COMMENT

T - 24 was held as a diffuse signature for 90 minutes which makes it very unlikely that it was a submarine snorting.

1205 B 335/075 T - 25. Diesel signature 13.9 Hz spacing C/C 170 to resolve bearing

CO COMMENT

Our area appears to be filling up with diesel powered shipping: T-25's is not a threat frequency. B-355 T-25

1335 C/D PD Routine, fix, listen out for NIMROD

1340 Listening out for NIMROD - 10 minutes on each frequency

1355 B - 160 S - 16 Faint IN/OUT audible From gram 1 X 4 156 rpm

1406 C/C 140 to close S - 16

1550 C/D 260 C/S 15

CO COMMENT

No sign of the NIMROD. COR 292 is in. Going deep to close S - 16

B 170. S - 16 Blade flutter, IN/OUT - M/V C/C 180 to steady bearing rate.

1610 B - 162 S - 16 faded. Will continue to run down the bearing to try to regain contact

1628 C/S 5 - Nothing heard on S - 16



1634 C/D 180 to listen above the layer

CO COMMENT

Possible that S 16 was detected after CPA and has outrun me. Intend heading in a southerly direction making ground towards most likely area through which an ARG 'Breakout' would pass.


- 1716 T-26 Broadband pattern. 11.4 hz spacing in low band. Could be T-24 regained.
- 1725 C/C 270 to resolve bearing ambiguity
- 1734 B 125. T 26 Ambiguity resolved
- 1735 B 110 S 20 Audible ship contact 1 X 3 234 rpm IN/OUT M/V
- 1740 C/S to C/C 080 to range on S 20
- 1749 S 20 FCS (poor) 105/18 kyds 070/15 A0B 160 Port
- 1845 CO COMMENT

S-20 (classified M/V) is going East faster than us - not an interesting contact. Returning to patrol to West.

- 1852 C/D 260 C/S 15 C/C 240
- 2000 Position 46 12.1S 54 26.3W
- 2013 C/D PD Fix, Reruns of COR 293, 294, 295, 296
 Weather. Wind 20 knots from 210 Vis 5 NM
 Seastate 4 from 210 SSS 5
 Cloud 100% SVP 020 4910
 140 4910
 190 4870
- 2016 Sunset
- 2312 C/D 200 C/C 220 COR 294, 295, 296 received. Requested rerun 293.

CO COMMENT

1. Groupers are taking a long time to crack. COR 295 - Loses me Areas to the North in preparation for Point Four (VALIANT's) arrival. She is now on COR numbers, so that should ease the HF reception for me.



HK EYES 'B'

2. Since the area is quiet, I am conducting a controlled SCRAM and RC entry to check out the previous work on the steam leak drainage cachment and to take some measurements for a plate to stop the leak.

CO DAILY SUMMARY

- 1. Again very quiet. Two possible ship contacts S-16 and S-20, both classified as Merchant Ships. Unable to visually identify them.
- 2. COR 295 has restricted my areas in preparation for VALIANT to the North. I will be placed at "Centre Half" in the SSN Team and can therefore expect a very dull period ahead.

SUNDAY 16 MAY 1982

0220 B 155 S - 29. Possible hydroplane noise

0235 C/C 100 to put S - 29 in Broadcast Beams for Active Transmissions. Weapon Readiness State 1. Gyros running up blanking Sonar.

0250 B - 168 Possible 2 pens HF contact ■ S.29 C/D 425 to investigate below layer

0255 S - 29 FCS (Poor) 172/4 kyds 026/6 A0B 34 Port

CO COMMENT

Only this possible plane noise held. Nothing on the Towed Array - so if it is a submarine, it is a conventional one. Worst solution puts me right under foot. Will conduct a retiring turn to put S29 on the opposite beam to open my DOT. It will also give me a ranging manoeuvre.

0309

C/D 200 (Layer depth 240') S - 29 appeared fainter below layer.


CO COMMENT

- 1. Options are that the contact might be:
 - a. SSN most unlikely since there are no other clues on any other sonar
 - b. SSK perhaps, but where has it come from?
 - c. US don't believe so now, although I did to start with
 - d. Bio possible


SEGRET

: | UnCLASS/mPM |

UK EYES 'B'



SECRET



UK EYES 'B'

- 2. The options that I have are:
 - a. stay here and monitor it while trying to range and track it
 - b. Go active not vet
 - c. Close not too happy about doing this yet

Therefore intend remaining at slow speed in the layer, monitoring S-29 and trying to get a better classification

B - 170/280 49.6 and 50.1 Hz on array. Held for 4 minutes B - 172. S - 29.

CO COMMENT

This tonal could be S - 29 or us. Not held for long enough to investigate

0359 S - 29 not heard for 9 minutes C/D 260 C/S 7 C/C 195

CO COMMENT

Intend running down the bearing for up to 1 hour to see if I can close.

-0410 B 113/277 50Hz line on array

CO COMMENT

This would indicate that the Tonal is from B-277 and not associated with S-29.

0436 C/S 10.S - 29 only occasionally audible. There is no pattern to the noise.

0445 C/C 110 to try and move the bearing of S - 29


C/C 195. S - 29 not heard for 5 minutes.


0515 C/S 6 to listen for S - 29. Not heard for 24 minutes

CO COMMENT

S - 29 now sounds different and more complex. Possibly a number of tones audible. Getting louder.

3 transmissions, Position 13 - No contacts.





O600 C/C 280 to produce a left bearing movement on S - 29 C/D 160 to listen above layer - no change

0612 C/D 425 to listen below layer - no change

0617 3 transmissions Position 13 - B - 216 R - 64 kyds, Probable bottom

0625 C/D 260 C/S 15 C/C 000

CO FINAL COMMENT

Classification is not really based on very much except a "feeling in the water". The only thing it could be, if a submarine, is plane noise. There is no other characteristic on it on any sensor. Therefore not SSN and not SSK at PD, since no in/out, cavitation etc. If it is an SSk it is Deep; but course and speed of contact for four hours seems to have been about 190 - 9 knots, a little fast. In addition, intelligence would suggest no ARG SSK in area. Therefore Non Sub, but I know not what. Look forward to JAAC's thoughts on contact! Intend clearing area to the North before returning to PD.

0724 C/D PD Routine and fix.

0800 Position 46 48.7S 54 56.0W

Weather Wind 15 knots from 270 Vis 5 NM
Seastate 2 - 3 from 270 SSS 1 - 2
Cloud 100% SVP 020 - 4907

150 - 4907

190 - 4875

1020 Start ventilating

1053 Sunrise

1732

1110 Stop ventilating. C/D 200 C/S 10 C/C N - clear SNORT Datum.

Signals received COR 293 (rerun), 297, 298

1532 C/D PD Routine and fix

730 Traffic received COR 299 - 302


CO COMMENT

This suggests that the CVA might be near RIO GRANDE - our old area !!

B - 153. S 05 audible ship contact

Op 200 Of 120 to investigate

B-156 S - 05 - medium diesel M/V Very long range



1

SECRET UNCLASS/NPM

2000 Position 46 29.4 S 55 44.9W

2015 Sunset

2100 C/D PD. Routine, Fix, domestics, ventilate and listen out for NIMROD on ASV search

Weather Wind 10 knots from 270 Vis 3 NM
Seastate 2 from 270 SS 1 - 2
Cloud 100% SVP 020 - 4890
170 - 4890

2315 Traffic received COR 303 - Area reallocation - I lose areas to East.

Send more Sitreps!

COR 304

ZID cleared

2316 C/D 200 C/S 6 C/C 270

CO COMMENT

No sign of NIMROD

2359 CO DAILY SUMMARY

- 1. Quiet day, with the exception of S-29 during the morning, there was nothing of interest. My final classification of that was non submarine, but I know not what.
- 2. We seem to have lost the CVA.
- 3. COR 303 has slightly bottled me up to the west to allow VALIANT south. Also it would appear that I am sending insufficient sitreps but difficult to make something of nothing.

MONDAY 17 MAY 1982

0214 B - 050 S - 72. "Plane noise".

CO COMMENT


S - 72 is the same noise as S - 29 which was heard 24 hours ago (to within 5 minutes). Still no idea what it could be.

0236 C/D PD Routine and fix.

Traffic received COR 304, 305, 306.

SECRET.







C/D 200 0400

C/D PD Routine. Fix and snort ventilate 0758

46°29'.48 57°01'.8W Position 0800

> Weather: Too dark SSS 3

> > SVP: 020 - 4870

180 - 4870

0807 Start ventilating

CO COMMENT 0830

> Left old set of areas 4 hours early Received COR 307, 308 (NIMROD flight details)

0908 Stop ventilating

C/D 200 Intend to head for centre of my patrol area 0922

1048 Sunrise

1507 C/D PD Routine and fix

> Wind 10 knots from 020 Vis 0.5 NM (Fog) Weather:

> > Sea State: 1 from 018 SSS: 3

Cloud: 100%

CO COMMENT

Received COR 309 via SSIXS! Intend 10 knot transit to SW of my area in anticipation of the new water to be allocated to cover NW approaches to Falkland Islands for forthcoming landing.

C/D 200 C/C 235 - heading for new area 1555

2000 Position 47°00'S 58°30'W

Sunset 2027

C/D PD Routine, fix and ventilate <u> 2125</u>

Weather: Too dark


SVP: 020 - 4870SSS: 3 080 - 4853


110 - 4853

135 - 4845

190 - 4845

2133 Start ventilating





. }

1.1



Possible I Band racket on YAF (not audible, no bearing) <u> 21 35</u> fits Boeing 707 Stop ventilating

Warner clearance - no rackets 2148

Boeing 707 again on YAF 2149 C/D 260 C/S 12 C/C 270

CO COMMENT

Intend staying deep for 1 hour to further investigate the warner interference and to allow the possible 707 to clear the area.

C/D PD Routine, Fix and ventilate 2322

CO COMMENT

HF and VLF reception on the wire is very poor, there is obviously Intend opening 60 NM to the East and to surface some water ingress. to repair or change the wire.

CO DAILY SUMMARY 2359

The HF reception problem could just be the HF Another quiet day. tail which I can easily replace, or the watermate connection which My fingers are crossed for the former. is the worst case.

TUESDAY 18 MAY 1982

C/D PD to surface 0307

No rackets, no visual contacts. Vis 1NM (Mist) 0320

Emergency UHF aerial rigged for SSIXS 0321 Surfaced: 1.


HF tail on - floating wire (AHG) changed, but no 2. improvement

Two replacement AHG's also defective

CO COMMENT

- Emergency UHF aerial is excellent gives one an SSIXS insight into what joy a trouble free comms patrol might be like.
- Intend HF reception is now worse than when I started. diving to allow the maintainers to attempt repairs on all three wires. This requires resoldering at the outboard Dielectric, which is not believed possible onboard.

The ability to make the end product watertight is also doubtful.



0603 Dived C/D 260

Position 46 46.3S 57 34.4W 0800

Weather Unassessed SSS 2

SVP 020 4880 260 4879

300 4870

400 4860

700 4825

C/D PD 0914

0923 Surfaced to stream a repaired AHG

1013 No reception on AHG

CO COMMENT

Repair of first wire was unsuccessful. Diving now as it gets Intend surfacing to stream light to attempt repair on second wire. it as soon as it is ready.

1037 Dived

1110 Intend remaining within 10 NM at 46 50S 57 30W

1111 Sunrise

1725 C/D PD. Attempt to receive Routine on SSIXS and fix

2000 Position 46 54,1S 57 22.0W

> Weather: Wind 5 knots from 110

SSS 1 - 2 Seastate 1 from 110

Vis 1 NM

Cloud 100%

2022 Sunset

2320 No rackets, Nothing visual. Vis 0.5 NM (Mist)

<u>2322</u> Surfaced to stream repaired AHG.

<u> 2359</u> CO DAILY SUMMARY

This has most probably been the most frustrating day of the Patrol. We were all set to move West into water where the ARG Warships are thought to be, when reception on the HF tail on the floating wire started to show signs of deteriorating. I therefore withdrew 60NM to the East to surface in order to replace it with one of the other On surfacing these were both found to be damaged by two I carried. water ingress - Why? Brought all three below to work on them, but successful repair seems unlikely.

UNCLASS/NPM

UK EYES 'B'

I then had to watch the water to the West of me be reallocated to VALIANT, so that I now sit with an SSN buffer between me and any chance of some action. Present indications (confirmed at 190050) show that all 3 wires are just as useless. The result - I have wasted at least 36 hours operational time, lost the water where I might do something useful and now have to sit in a passive posture, not the best employment of an SSN; all because of the inability to repair an HF wire.

The Good News!? - SSIXS, that has not worked for over a week, decided to come good when HF went down - again without any technical explanation forthcoming. Let us hope I am allowed back in before it is too late.

Today received COR 311 that says we will be off station 2 June and back 25 August. I have many thoughts for improving my comms fit which will be actioned before I return.

WEDNESDAY 19 MAY 1982

0015 No new traffic on SSIXS via emergency UHF aerial

0025 Dived C/D 200

CO COMMENT

All three wires tested and the best one streamed although it is not correct. Intention is to catch a trim at 200 feet and then return to PD to test HF reception.

0046 C/D PD No reception on HF tail

CO COMMENT

The best wire does not work. The last 20 hours plus seems to have been wasted. I am now relying on intermittent SSIXS. (See CO DAILY SUMMARY on 18 May for full thoughts).

0050 C/D 200 to continue ASV Patrol

O300 C/D PD for Routine, Fix and domestics COR 324 (NEPTUNE heads down) received

0510 C/D 200

SECRET B-131

UK EYES 181

UNCLASS/NPM

0800 Position 47 29.7S 57 59.5W

0902 C/D PD Routine, fix and domestics

Weather: Too Dark

160 4880

SVP 020 4880

Traffic received COR 323 - NIM

COR 323 - NIMROD COR 325 - pt 4 Buffer zone

CO COMMENT

SSIXS is working well! Have received an extract of the News too which tells me that the TASK FORCE has been placed on Active Service since Saturday 15 May - the last time was in the early 1960's.

0950 Nothing heard from the NIMROD mentioned in COR 323.

<u>1106</u> C/D 260


1113 Sunrise

JEZ Buoy sighted - R 20 yds. Position 47 32S 57 57SW C/D 700 C/S 21 C/C 260

CO COMMENT

00W sighted JEZ buoy close - went deep on magnetic West to clear Datum. Intend opening 'off - track' to NW for 6 NM and then running West for a further 45 minutes,

No intelligence of aircraft in the area, no rackets for 4 hours and no indication that they might have searched this part of the world before. Unlikely that it is still active



C/C 320 1300

C/C N Start 'GRANNIES - FOOTSTEPS' - 200 every 10 minutes back 1314

C/D 260 C/S 5 SVP 020 - 48451416

260 - 4837

300 - 4837

380 - 4825

640 - 4825

Interference on Warner I Band is getting worse; investigating the 1501

probable cause which is the test source

C/D PD Routine and fix 1645

Received - COR 326 - Area Sitrep

327 - Heads Down

328 - Weather Report

C/D 260 1806

2000 Position 47 24.8S 58 36.4W

Sunset 2025

2128 C/D PD Routine, Fix and domestics

Weather: Wind 15 knots from 000 Vis 5 NM

Seastate 2 from 000 SSS 5

SVP 20 - 4845 Cloud 100%

180 - 4845

Traffic received COR 239 - Family grams for Pt ONE/TWO!

C/D 260 2200

2359 CO DAILY SUMMARY


Quiet day patrolling the Area.

THURSDAY 20 MAY 1982

C/D PD Routine 0057

Received COR 330, 332. 334 not on the routine yet, probably the

daily sitrep grouper



CO COMMENT

- Reminds that I am a shield and not a Lance! COR 330 1. At least I feel more confident I am doing something useful.
- Working on CO2 Scrubber problem appears to be fixed but CO2 is high.
- Stopped work on trying to cure problem on I Band. 3.
- Moving towards the centre of my patrol area.

C/D 260

C/D PD Routine, fix and domestics

Position:

47 09.55\$ 57 35.9W

Weather:

Wind 20 knots from 030

Seastate 3 from 030

Vis 8NM SSS 6 +

Cloud ZERO%

SVP 020 4877 260 4876

380 4864

Traffic received COR 333 - NIMROD/Intentions

N/NCTG 318.7 - Morale Booster

C/D 260


Sunrise

C/D PD Routine and fix

CO COMMENT

- At PD for 6 hourly weather report. 1.
- All night we have been in a high CO2 environment. CO2 leak on scrubbers has produced 4 more, however I believe the problem is fixed and CO2 should start to fall again.
- Spent all night working to remove I Band interference on WARNER 3. - probable cause is in the mast. Filter fitted that seems to be cutting it down.
- 4. What next!?

COR 334 - ARG gunnex close to coast vic 5130N COR 335(v) - Area change Point One - she covers San GORGE Bay







1310 · 20 - 30 GLOBICEPHALE MELAENA astern!

1334 C/D 200

1535 B - 310. T - 59 Poss shaft rub - associated with WP F/V

1615 T - 59 faded

1732 C/D PD Routine and fix

1815 Traffic received COR 336 - Landings are on

BOUCHARD off RIO GRANDE

COR 337 - A/C flights from RIO GALLEGOS

CO COMMENT

The landings are now on in SAN CARLOS water (Operation SUTTON)

1920 Weather: Wind 10 knots from 350 Vis 3 NM

Seastate 3 from 350 SSS 6

Cloud 100% SVP 020 - 4880

140 - 4880

160 **-** 4867 200 **-** 4865

2000 Position 47 04S 57 21.5W


2020 Sunset

2340 C/D PD Routine and fix

2359 CO DAILY SUMMARY

1. Very quiet day.

- 2. Todays defects were the CO2 scrubber discharge system. When one leak was investigated; four more were found. This resulted in the atmosphere being out of spec for CO2 for 15 hours. The Warner Mast developed yet further interference which tends to restrict my search to below PD.
- 3. Initiation of Operation SUTTON is great News!!



FRIDAY 21 MAY 1982

0245 C/D 200

CO COMMENT

COR 339 is a very long grouper. Have obtained 9 garbled copies from which I hope to patch together a good one.

0555 C/D PD Routine and fix

CO COMMENT

Clear night. Will remain at PD for Visual, ESM search

0748 B - 320. Bright white flash

B - 317. S - 16 faint audible contact, could be associated with the flash

0757 B - 245 Second flash

CO COMMENT

Several white flashes have been seen between 245 - 320. All very brief, either gunfire or lightning Due to the lack of consistent bearing, classified: Lightning.

0800 Position: 46 54.7S 57 35.9W Vis 6NM

Weather: Wind 15 knots from 010 SSS 3 - 4

Seastate 2 from 010 SVP 020 - 4883 Cloud ZERO % 260 - 4880

Traffic received COR 339 - Good long ARG Sitrep

COR 341 - Assessment of ARG Options

COR 342 - Political Situation

CO COMMENT

Have spent all night trying to receive and break COR 339 (1078 groups) a 341 (480 groups). They were worth it.

0844 C/D 200


B - 328 S - 16 Best estimate of Range 50 kyds. Only BIO audible


0905 S - 16 FCS (Poor) 327/45 kyds 070/12 AOB 77 Stbd

0940 B - 339, S - 16. Nothing audible. Intend sprinting down the bearing to close

C/D 425 C/S 15 C/C 000







1020 B - 350 S - 44 (S - 16 regained) Not audible. Range approximately 32 kyds, contact is on Easterly heading, quite fast speed.

CO COMMENT

I do not intend pursuing this contact as he is well outside my area. If he appears to move South I will think again.


- 1112 Sunrise
- 1136 C/D PD C/S 5 C/C 090 Routine and fix
 Nice clear day
 COR 343 (only signal) -Our weather reports are appreciated, plus
 Tigerfish Mod 1 recommendations
- 1244 C/D 200 C/C 270
- B 347/193. T 67 Very unstable (Shifts of up to 25 Hz seen) gearing line C/C to resolve ambiguity
- 1422 B 347. T 67 C/C 010 to close T - 67
- 1540 CO COMMENT

After a 40 minute run at 15 knots, no change in intensity of T-67. Intend remaining in my present position until 1700 before returning to PD. If nothing further on T-67 or going deep again, I shall return to the South and wait for her to come to me!


- 1615 B 347 S 06 Could be associated with T 67
- 1645 C/C 050 C/S 12 ranging on S 06 FCS (Poor) 332/50 kyds 220/15 A0B 48 Port
- 1849 C/D 200

Weather: Wind 20 knots from 230 Vis 8 NM
Seastate 3 - 4 from 230 SSS 4 - 5
Cloud 10% SVP 020 - 4877
180 - 4877

Received COR 344, 346, 347 - Unimportant and COR 345



UK EYES 'B'




CO COMMENT

- 1. It has taken me $1\frac{1}{2}$ hours to get 2 groupers (400 groups each). Comms certainly teaches one patience!
- 2. The way T 67 has come and gone all day suggests to me that it is a WP F/V starting and stopping rather than a. W/S closing me. However the continental shelf is 180NM away down the bearing.
- 2000 Position 47 12.4S 57 19.4W
- 2022 Sunset
- 2030 B 347 T 67 Possible Type 42 gearing line?
- B 347 T 67 faded suddenly stopped?
- 2200 CO COMMENT

Still no sign that contact T-67 is of interest. She has not apparently closed during the last 12 hours. Moving to South, back into centre of my Area. If it is a warship then it will come to me later.

- 2219 C/D 425 C/S 21 C/C 190. Running for 1 hour before surfacing to stream a new wire.
- 2330 C/D PD C/S 5 C/C 090
 No contacts sonar, No Rackets
 Weather: Wind 15 knots from 230 Vis 6 NM
 Seastate 3 from 230 SSS 6
 Cloud 10%
- 2344 Surfaced start circling to Port
- 2359 CO DAILY SUMMARY
 - 1. Spent the first part of the day investigating Tonal. T 67 to North of me. Although it can not be written off as non threat, she is still a long way North. Therefore moved back to centre of Area.
 - 2. Surfaced (again!) to stream one of the newly built HF wires (iaw COR 340).



SATURDAY 22 MAY 1982

0019 ' Dived - C/D 200

0030 Some HF reception (low frequencies only)

0035 C/D PD

0040 No reception on wire

OO54 Very loud cavitation - OSN, possibly floating wire around the propeller. Going ahead/astern will not clear it.

CO COMMENT

The surface and dive to restream an HF wire went very smoothly. However it was too rough to put anyone on the casing, so the old wire was released overboard. On diving and speeding up, strong cavitation from us was audible above 7 knots. I must presume that one of the two wires is now wrapped around the propeller. It is too rough to put Divers down at present, I shall have to wait for the weather to improve.

In the meantime, it is very restrictive and gives an excellent opportunity for counter detection by SSK/JES/etc.

0135 C/D 200 C/S 8 C/C 180 - Heading towards centre of area

O535 C/D PD C/S 5 Routine and fix B - 305 T - 67 is still here!
Possibilities for T - 67:-

1. F/V FCS (Very poor) 305/160 kyds 250/8 A0B 125 Port

2. Type 42 FCS (Very poor) 305/90 kyds 180/18 A0B 55 Port

Solution 1. More likely as it puts the contact on the 100 fathom line

0730 Received COR 349 - 355


0753 B - 090 Bright white light; possible A/C coming straight towards
(In position 47 08.8S 57 13.2W)


C/D 700 C/S 21

ACTION STATIONS

(No rackets during the $2\frac{1}{2}$ hours at PD)







CO COMMENT

- 1. Took 2 hours 20 minutes to achieve COR 349 355.
- 2. The Battle on the FI seems to be going well, but the surface ships are suffering
- 3. While shallow for final Satellite Challenge, the 00W saw a bright light ahead and the submarine went deep to evade, presuming the worst.

No MPA thought to be in the area, but with Warner I Band suspect, I decided it was best to evade for 1 hour to the SE using "GRANNIES FOOTSTEPS".

No reaction sighted

Assessment:

MPA with searchlight on (Why?), or

Planet JUPITER

4. Cavitation continues.

0800 Position 47 08.8N 57 13.2W

0845 B - 307 R - 26 kyds. Datum of sighting aircraft

No sonar contacts

Fall out Action Stations

0850 C/D 425 C/S 8 C/C 185

0900 B - 308 T - 67 and S - 90

1000 C/C 340 to range on T - 67 and S - 90

1010 Range greater than 70 kyds

1112 Sunrise

1145 C/D PD Routine and fix

Weather: Wind 15 knots from 250

Seastate 2 from 250

Deastate 2 110m 2)

Cloud 30%

Vis 7.5 NM

SSS 4

SVP 020 4882

280 4882

360 4870


515 4825

670 4825

SECRET-

B-145 ·

UNCL**AS**S/NPM



1230 COR 356, 357 received

CO COMMENT

COR 356 reminds me that we straddle ARG SSK route P BELGRANO - FI, - just the reminder I need with my cavitation problem.

1256 C/D 200

1740 C/D PD Routine and fix

Weather: Wind 15 knots from 340 Vis 10NM Seastate 3 from 325 SSS 4 - 5

> Cloud 30% SVP 020 - 4867 180 - 4855

Traffic received COR 359 - Target Int COR 360 - Heads down

1824 C/D 200

2000 Position 47 32.5S 57 38.1W

2015 Sunset

2045 C/D PD to assess weather - Too rough to put divers into the water Received COR 363 - Air assessment
362 - Cup Final Results


2148 C/D 200


2354 C/D PD Routine, Fix and Domestics Received COR 361, 363


CO DAILY SUMMARY .

- 1. A quiet day.
- 2. My cavitation problem gives me cause for concern. As soon as the weather is calm enough I shall surface to put a diver into the water to investigate because at any speed above 6 knots I sound as though I am trailing a metal dustbin.

SECRETI B-146 IIK EYES B







UK EYES 'B'

UNCLASS/NPM

SUNDAY 23 MAY 1982

0045 C/D 200

O220 CO COMMENT

Conducting further investigation into the shaft noise. There is a possibility that some of this noise is internal and not due to the suspected wire around the propeller.

0345 CO COMMENT

Tightening a possibly loose bolt on the torsion meter has reduced the noise, but the rasping sound is still present

0350 B - 116 T - 78 390 Hz unstable line, possibly gearing associated

0352 C/D PD Routine and fix

0700 Received COR 365 - 368

1. Position of BUENO, BOUCHARD, SEGUI, BAHIA PARAISO

2. Area allocations Sitrep

3. Amphibious Landings Sitrep

0800 Position 47 26.4S 57 30.4W

Weather Wind 10 knots from 000 Vis 10 NM

Seastate 3 from 080 SSS 4 - 5 Cloud ZERO% SVP 020 - 4880

180 – 4885

1113 Sunrise

1153 C/D PD Routine and fix

Received COR 369 - 371

CO COMMENT

COR 371. First Heads Up that ARG Warships may be preparing to sail from Port BELGRANO. Moving North in anticipation.

1253 C/D 200

1746 C/D PD Routine and fix

SECRET UNCLASS/NPM

1805 B 306/236. T - 87, Possible diesel signature, 12.5 Hz spacing B 352/188, T - 89 Possible diesel signature, 10.5 Hz spacing

1844 C/C 015 to resolve Tonal Bearings ambiguity

1900 B - 296. T - 87 (T - 89 faded)
B - 295. S 22. Held passive only, possibly associated with T - 87

CO COMMENT

COR 372 gives a secret format for reporting aircraft detection. This is really excellent news as it will mean less groupers. It should reduce my time challenging SSIXS.

1933 S 22/T - 87 FCS (LOP, VERY POOR) 1. 298/16 kyds 025/7 AOB 93 stbd 2. 295/24 kyds 070/10 AOB 48 stbd

1935 S22/T - 87 1936 Range 60 kyds Classificat on - Probable Long Range M/V

2000 Position 47 00.6N 57 31.5W
Weather: Wind 8 knots from 230 Vis 10NM
Seastate 2 from 215 SSS 1 - 2
Cloud 10% SVP 020 - 4877
180 - 4877

2016 Sunrise

2058 C/D PD - To surface if conditions suitable to put a diver in the water

No Rackets. Nothing visual. No interesting sonar contacts

2128 Surfaced. Disengage Clutch

2146 Floating wire recovered - about 120 feet missing from end


2147 Diver in the water


2150 Diver on the propeller
2207 Diver clear of the Water. Engage clutch

2217 Dived. C/D 200

CO COMMENT

1. Surfaced to put a diver into the water to remove the wire from around the propeller. Conditions were assessed as alright prior to surfacing, but once on the surface they were marginal. The Diving Supervisor was washed overboard but quickly recovered using his safety harness lifeline and the diver had to come out after 20 minutes suffer: from exhaustion. However he managed to cut two long 'tails' of wire away from the propeller. There is one 6 foot tail left plus an unknown amount still around 3 to 5 of the blades.





Fort 1

- 2. Recovery of the old wire showed it to have been cut, despite the correct precautions on diving.
- 3. On diving rev checks show that there is no cavitation at 60 revs or less and very slight up to 80 revs rapidly worse after that. I now feel happier about closing an SSK or ARG Warship to attack with less chance of counter detection.
- 4. PO(S)(SM) LIBBY, the Diver, conducted himself most professionally well beyond the call of normal duty and is to be commended.

2359 CO DAILY SUMMARY

- 1. I have an intermittent knocking/clicking noise from the shaft believed internal, but it may be a result of the wire around the propeller.
- 2. Signals suggest the Argentinians may be about to close the FI with their warships probably from the West (outside my area), possibly from the North (through my area).
- 3. I surfaced this evening in what turned out to be marginal Diving Conditions to cut free the AHG wire from my propeller. Although only partially successful, it has eased the problem of our cavitation.
- 4. A quiet day, limited to about 6 knots, searching my area.
- 5. I am now patrolling centre of area with the thought that tomorrow could bring some action.

MONDAY 24 MAY 1982

OO12 C/D PD Routine and fix
No new signals

0033 C/D 200

0548 C/D PD Routine and fix

Received COR 380 - NEPTUNE Racket

NN -BANDEIRANTE racket from Point ONE


Nothing else - A quiet Sunday night!


0619 C/D 260

0737 B - 319 S - 68 Audible ship contact. Blade flutter (Faint)
162 rpm. IN/OUT - probable F/V

CO COMMENT

Part of the fishing Fleet on the 100 fathom line





0800 · Position 47 03.4S 58 12.3W

Weather Wind 15 knots from 010

Seastate 2 - 3 from 010

Cloud 60%

Vis 8 NM

SSS 4

SVP 020 - 4885

175 - 4885

190 - 4862

250 - 4852

1120 Sunrise

1156 C/D PD Routine and fix

CO COMMENT

- 1. The sea and swell have definitely increased since sunset last night so we were fortunate we took the opportunity to work on the propeller when we did, as it is now too rough again.
- Signals received COR 381 384
 - 1. BOUCHARD/BUENO still on radar picket duty off RIO GRANDE
 - 2. The Northern Group are still in P BELGRANO Area, perhaps they are preparing for something.
 - 3. Have spent nearly two hours at PD receiving traffic also conducting ESM/Visual search. As I would expect in this area no activity. I think 200 feet is a better search depth so am returning deep to continue ASW/ASV search.

1405 C/D 200

1730 C/D 750 for Bathy

1815 C/D PD Routine and fix

Weather: Wind 10 knots from 340

Seastate 2 from 340

Cloud 90%

Vis 12 NM

SSS 2

SVP 020 - 4855

200 - 4855

400 - 4820


750 - 4820

*Traffic received COR 385 - 79.3 movements

C/D 200

Position 46 40S 58 18.2W

SFCRET UK EYES 'B'



UK EYES 'B'

UNCL**AS**S/WOM

2021 Sunset

2352 C/D PD Routine and fix

CO DAILY SUMMARY

A quiet day. Only contacts are the Warsaw Pact Fishing Fleet to NW.

TUESDAY 25 MAY 1982

OOO3 C/D PD Routine, fix and Domestics
Only traffic. Locating Report from Pt ONE of a BANDEIRANTE racket

0114 C/D 200

0340
B 302 S11 F/V
B 330 S12 1 X 4. 102 rpm M/V (Possibly Factory Ship)

CO COMMENT

These contacts are part of the Warsaw Pact Fishing Fleet. However I'm not convinced about S12, so am monitoring.

0445 B 350 S 12 beginning to move right

0510 S 12. FCS (Poor) 000/18 kyds 110/12 A0B 70 Stbd

0545 S 12. FCS (Poor) 020/20 kyds 080/2 A0B 120 Stbd

CO COMMENT

This is a M/V opening to the NNE, past CPA.


O615 C/D PD Routine, fix and Domestics
No new traffic
S 12 faded

0651 . C/D 650 S 18 FCS (Poor) 085/28 kyds 120/12 A0B 145 Stbd This is S 12 regained


0702 C/S 21 C/C 090 - to close S 18

CO COMMENT

Men at PD, considered a possible solution for S 18's |S 12) course might be 150 - 170. Therefore decided to attempt to close to confirm she is not a threat to TG 317.8



UNGLASS/NPM



C/D 260 C/S 6 0800

B - 100. Faint contact, possibly S 18

Position 46 23.6S 57 45.5W

C/D 650 C/S 21 C/C 120 Sprint to close S - 18 0808

C/D 260 C/S 6 S - 18 not regained 0932

CO COMMENT

S - 18 classified M/V. Destination unknown - she probably altered course to the NE some time after 0700Z.

C/D 650 C/S 21 C/C 285. Returning to centre of my patrol area. 0941

C/D 260 C/S 8 1100

Wire induced noise heard on slowing down, loud between 18 - 13 knots, not present below 9 knots.

Sunrise 1117

1157 C/D PD Routine and fix

> Weather: Wind 15 knots from 220 Vis 10 NM

Seastate 2 from 220 SSS 2 Cloud 10% SVP 020 - 4876

040 - 4878

Signals received COR 386 - 390

COR 387 - Argentinian Sitrep. Suggests they are still not prepared to let their Navy play. One of their SSK's might be coming our way within the next few days?

1512 C/D 200

C/D PD Routine and fix 1805

1826 B - 130.One Loud Bang (Nothing Visual)?

1915 CO COMMENT

> It has taken me one hour to break COR 391, a small grouper. Contents about a S 209's TFX results/problems.

C/D 200 1933

2000 Position 46 26.5S 57 38.8W

Weather Wind 15 knots from 210


Seastate 3 from 210 Cloud 60%

Vis 10 NM SSS 5

SVP 020 - 4870 090 - 4870

150 - 4865





UK EYES 'B'

UNCLASS/NPM

2017 Sunset

C/D PD Routine, Fix and Domestics 2353 Received COR 392 - SPLENDID's subnote home.

CO DAILY SUMMARY

- Another Quiet Day. 1.
- S12/S 18 detected and classified as a M/V opening to the The only other contact I found of interest is around a bearing of 035 held throughout most of today on passive LF only.

WEDNESDAY 26 MAY 1982

C/D 200 Traffic received COR 392 0020

B 137/043 T - 080025

C/C 330 to resolve ambiguity

B 137 T - 08 Possible gearing line 0100

CO COMMENT

Only vessels known to be to SE are the UK Group - 250 NM away. Possibly this is a CZ detection of them. It is marking very strongly.

B 140 T - 08 showing 376, 387.8, 550 Hz lines 01 25

C/C 050 to investigate T - 08

T - 08 not regained after the alteration 0150


Faint explosion heard sector - no bearing 0225


0255 Second faint explosion heard - no bearing

Nothing further on T - 08 0300 C/C 260 to centre of patrol area

B - 136 T - 08 regained <u>0320</u>

IIK EYES'B'





T - 08 faded 0400

C/D PD Routine, Fix and Domestics 0558 Traffic received COR 394 - NIMROD surface search

Listening out for NIMROD's Blind broadcast - nothing heard 0640

B - 010 Dangerous I Band racket. E - 28 PRF 375 PW 1.2 0641 Poss Searchwater

CO COMMENT

E - 28 is the NIMROD from COR 394, ETA 70 NM NE of my present position at 0600, then tasked to fly due west. Therefore E - 28 should move left.

B - 270 E - 28 PRF 750/350 Pulse compressed ARP5 Searchwater 0658 Nothing heard from the NIMROD

CO COMMENT 0759

Have spent the last 2 hours trying to patch together a grouper - only to find it is for ONYX. No sign of COR 393, it must be the daily Sitrep grouper. However ONYX's signal was a sitrep of yesterdays fighting. A sad day for the RN.

Position 46 38.5S 58 01.4W 0800 The shaft click is now held as a tonal, centre frequency 480Hz. However the seastate is low. Possibly surface reflection Weather - as at 1200

C/D 200 0830

1117 Sunrise

B - 315 T14 - 12.5 Hz spacing 1156 B - 342 T13 - 6.5 Hz spacing

CO COMMENT

T 13, T 14 believed to be associated with the WP F/V's Will monitor just in case they are different

C/D PD Routine and fix 1208

Weather Wind 15 knots from 300

Vis 10NM

Seastate 2 from 300

SSS 2 - 3

Cloud 40%

SVP 020 - 4875

260 - 4875

T-13, T-14 lost on return to PD



