2. Troubleshooting

Check vibration level monthly.

MOTOR VIBRATION ANALYSIS

ALIGNMENT TOLERANCE MAX 45 MM PER SECOND