



## Health and Safety Windsor Report

Generated By: John McGann Generated On: 03/03/2010 - February

## LTA



## Safety Opportunities



In the Coating Dept. on Coater #2, two operators attempted to remove a start-up roll from the rewind which had telescoped and covered over the roll shaft extension on one end.

The operators rigged 2 narrow lifting slings and speader bar to lift the large roll, and the sling on the telescoped paper side slipped, causing the roll to drop from the hoist.  $\Box$ 

Potential for severe injury to employees if struck by falling roll.  $\square$   $\square$   $\square$   $\square$   $\square$ 

The Department group reviewed this event and it's causes at Dept. Safety Tool Box Talk briefing.

Management counseled all operators to use wide body fabric lifting sling to fully support large rolls if roll shafts are not completely exposed and roll shaft ends cannot be securely held with narrow slings, when removing rolls with ovehead chain hoist.