

Doc No:	QD278
Revision No:	1.0
Revision Date:	27 Feb 2024
Approved by:	GM, Admin & Logistics

VEHICLE JOB ORDER FORM

Driver's name: Pool car Date: 17/09/2024
 Car Plate No: LSR 289 26 Job Description: Servicing/Repairs/Replacement
 Car assigned to: Lekki Pool car Office: Depasa

Driver's Complaint:

s/n	Description	Fleet Supervisor's remark/observation
1	Car movement is very bad with disturbing noise from underneath the car.	The vehicle front shock absorber and bushing linkage, engine seat need replacement.
Chief Driver's remark	Diagnosed to the Front shock absorbers, arm bushing, linkage and engine seat.	
Signature & date	<u>[Signature]</u> 17/09/2024	
Recommended Mechanic	TUNKAS AUTO MECHANICAL	

GM ADMIN & LOGISTICS'REMARK (if any):

APPROVED/NOT APPROVED

