

Final Technical Report — DME Status with TLS System

Subject: Clarification regarding DME availability during test flight

During the latest test flight using a Cessna aircraft, all TLS functionalities were operating normally except for Distance Indication. The pilot reported that DME was not received during approach.

Point 1:

The TLS system is capable of calculating aircraft distance internally, however this distance cannot be received or displayed to the pilot unless a DME transmitter is installed and enabled.

Point 2:

External DME is required to transmit distance information to onboard aircraft receivers. The TLS system does not transmit DME information by itself.

Point 3:

The reason DME was not available during the last test flight was due to the DME being turned OFF at the ILS glide slope shelter.

Corrective Actions for Future Tests:

- Ensure that the DME remains ON and transmitting before any future approach tests.
- When the DME is enabled, distance information will be received by the aircraft normally.