Assembly Instructions

Robotic Arm

Material



Laser cutting plywood


3d printed PLA

Laser cutting PVC



steel





Parts



top x1















motor_link_xl x1

wall_front x1

















wall_side x2


fixing_base_tree x1

bottom x1

tree_base x1








Parts





small_gear_shoulder (25 teeths) x1



big_gear_shoulder (110 teeths) x1


left_side x1

right_side x1





SKF 7202 x2













motor small gear Screws: - M2 (12) x2






Screws : - M2 (12) x4 \mathcal{O}



 ∞




















fixing_AX





cover_rod x1











Parts




big_gear_wrist (50 teeths) x1

radius x2






small _gear_wrist (25 teeths) x1
















arm x1 Screw: - M5 (60) x1




5 Small gear Big gear

SKF 7202 x2















humerus x2













4 arm x1 Screws:





5 small gear big gear

SKF 7202

