



DOC #: BRCC&PCC/MGT/ FRM-008 ISSUE STATUS: 01

ISSUE DATE: DEC 30, 2019

ENVIRONMENTAL ASPECTS ANALYSIS REPORT

19/03/20 Location: Unit 1 & Unit 2 Date: Residual Risk Sr. Area / Activity / Risk **Assessment Aspect Control Measures Applied Process Department** O D 0 Category D C R **Controls** C R a) Make material wet where possible while Air 3 12 1 Dust 0 4 handling a) & b) Done 2 0 6 emissions b) Use Mask to avoid dust exposure Construction Admin Use ear plugs / ear muffs 2 2 Noise Noise 2 0 4 Done 0 2 4 low Cleaning of outside Air 3 Use Mask to avoid dust exposure 2 3 Admin Dust 0 4 Done 0 3 6 low mirror emissions a) keep material covered Air 4 4 20 4 Vapors 1 a) & b) Done 4 1 12 low emissions b) Use Mask to avoid vapors exposure Admin Paint & white wash a) Use spill tray for liquid handling Chemical Release b) Use spill kit to control spilled material 2 6 12 5 0 a) to c) Done 1 0 4 low spillage/Contamination c) Make sure liquid handling container is fit for to land use. Air 4 0 Use Mask to avoid vapors exposure 4 0 2 8 6 **Fumes** Done low emissions Welding & **EMD** grinding Isolate the area by welding hut or other means 2 7 3 0 3 0 6 Heat Heat Done low to protect surroundings from heat.





DOC #: BRCC&PCC/MGT/ FRM-008 ISSUE STATUS: 01 ISSUE DATE: DEC 30, 2019

ENVIRONMENTAL ASPECTS ANALYSIS REPORT

Location:Unit 1 & Unit 2 Date:19/03/20														
Sr.	Area / Department	Activity / Process	Aspect		Risk Assessment				Control Measures	Applied	Residual Risk			Significance
#				Category	О	D	С	R		Controls	o	D	C F	cance
8	EMD	Welding & grinding	Noise	Noise	4	0	6	24	Use ear plugs / ear muffs	Done	4	0	4 1	6 low
9	EMD	Machine or heavy object transfer	Smoke of crane/fork lifter	Air emissions	4	0	4	16	a) keep crane or fork lifter engine maintained b) Do prier inspection of crane or fork lifter c) Prefer battery operated fork lifter to use.	a) & b) Done	2	0	2 4	l low
10	EMD	Cleaning of smoke/heat detectors & ceiling	Dust	Air emissions	2	0	2	4	Use Mask to avoid dust exposure	Done	2	0	2 4	l low
11	Store	Material shifting on huge scale	Dust and smoke	Air emissions	3	0	4	12	 a) cover or pack material properly while shifting b) Wear mask to avoid smoke & dust. c) keep fork lifter engine maintained d) Do prier inspection of fork lifter e) Prefer battery operated fork lifter to use. 	a) to d) Done	2	0	4 8	3 low
Prepared By: Reviewed By: Approved By:														