

Maintenance Incident Report

Machine: CNC-Mill-200

Error code: E101

Description:

Operator reported a loud grinding noise coming from the main spindle housing during a milling run. Vibration increases noticeably above 2000 RPM and the noise gets worse the longer the machine runs. No visible smoke or burning smell. Machine was powered down as a precaution and taken out of service pending inspection.

Reported by: Line Technician, Shift 2

Date: 2026-09-11