

VEDANTA LIMITED – VALUE ADDED	Document No:	VL/IMS/PID1/
BUSINESS		INST/WI/09
INTEGRATED MANAGEMENT SYSTEM	Revision Date:	05/01/2022
Work Instructions for Checking of limit	Revision No:	06
Switches mounted on All Weighing Bins &	Page No.:	1 of 1
Coke Gates	_	

CHECKING OF LIMIT SWITCHES/PROXIMITY SWITCHES MOUNTED ON ALL WEIGHING BINS & COKE GATES

Objective: To check the limit switches/Proximity Switches mounted on the Weighing bins & coke gates.

Scope: This procedure is applicable to limit switches/Proximity Switches mounted on the Weighing Bins & Coke gates.

Reference: Limit Switch & Proximity switches Manual

Performance Criteria: Operation of limit switches/Proximity Switches of all weigh bins

Aspect for the Activity: Waste generation

Identification of Hazards:

Mechanical: Trapping between belts, trapping between gates, falling, Entanglement **Chemical:** Dust, Graphite

Hazard due to Human Behaviour/Human error: Not adhering to WI/ PPE, Alcoholism, starting job without informing control room, Carrying job impatiently, improper communication, Use on non-certified tools/equipment.

Refer: RISK /INST/06 & RISK /INST/17

Responsibility: Sr. Engineer Instrumentation/Associate / Inst Technician

PROCEDURE:

CHECKING OF WEIGHING BIN & COKE GATE LIMIT SWITCHES

- 1. Before carrying out work on limit switches/Proximity Switches of weighing bins/coke gates mounted over conveyors, inform production to take system in manual and put respective belt off.
- 2. Ensure the belt is stopped by pulling pull cord.
- 3. For carrying out work on limit switches mounted over CB5 conveyors inform production for clearance to Stop CB5 belt.
- 4. Keep communication between control room and 27mtr level.
- 5. After belts are stopped carry out work on the limit switches/Proximity Switches.
- 6. Ensure that there is no gap between gates when it is in closed condition so that material doesn't fall on belt when gate is close & correct weighment can be done.
- 7. Reset pull cord arrangement of particular belt and normalize belt operation.
- 8. Inform production after the work has been carried out and give clearance.

Prepared By:	Reviewed & Issued By:	Approved By:
Associate Manager –	Management	Head – Electrical &
Electrical &	Representative	Instrumentation PID1
Instrumentation PID1		
Signature:	Signature:	Signature:
Signature:	Signature:	Signature:
Signature:	Signature:	Signature: