

VEDANTA LIMITED – VALUE ADDED BUSINESS	Format No.:	VL/IMS/PP2MECH/WI/18
INTEGRATED MANAGEMENT SYSTEM	Revision Date:	05.04.2021
Work instruction for Boiler feed water line valve work	Revision No.:	02
	Page No.:	1 of 2

**Objective**: Boiler Feed Water Line valve fitting

Scope : Power plant

**Responsibility** : Engineer in charge and workmen at job

PPEs to be used : Helmet, Safety shoes, safety hand gloves, ear plugs and nose mask

# **Aspect-Impact**

Fumes, Temperature Health impactSteel Scrap Resource Depletion

### **Hazards Identified**

Mechanical Hazard Falling of object, falling from height

Physical hazard Temperature Electrical hazard Electric shock

Human behavior Improper housekeeping, Non use of PPEs, Alcoholism,

Height phobia

# Safety precautions:

- Avoid using mobile phone while working.
- Use appropriate tools required for the job.
- After job always do proper housekeeping.
- Always prevent body from line of action of force.
- Perform proper communication verbal and non-verbal as required.
- Cotton hand gloves, nose mask, white/black goggles should be used
- Proper checking of Welding machine, gas cutting set, grinding, cut off, flexible grinding machine, etc. to be done.

#### PRECHECKS:-

- Take work permit
- Ensure that feed pumps all discharge valves must be closed.
- Ensure feed water temperature is bellow 50 degree & PRESSURE IS ZERO.
- Ensure feed pump must be rack out.

### **PROCEDURE:-**

- Before get the clearance from operating department shift the all required material like welding machine, gas cutter, grinding machine, all tools and inform to electrical department for giving connections.
- Open insulation of the line for cutting the pipe.
- Ensure that all line will be drained completely.
- After draining the full line with the help of cutting set cut the line.
- With the help of grinding make v shape on the cutting edge.

Prepared & Reviewed:	Approved:	Issued:
HOD – Mech – PP	Head – Power	MR
05.04.2021	05.04.2021	05.04.2021



VEDANTA LIMITED – VALUE ADDED BUSINESS	Format No.:	VL/IMS/PP2MECH/WI/18
INTEGRATED MANAGEMENT SYSTEM	Revision Date:	05.04.2021
Work instruction for Boiler feed water line valve work	Revision No.:	02
	Page No.:	2 of 2

- Position the new valve and start welding the joint.
- After completing the joint do proper cooling of the same.
- Remove the all machines/ tools / waste and shifted to proper designated areas.
- Close the work permit and hand over the operation for leakage testing.

Prepared & Reviewed:	Approved:	Issued:
HOD – Mech – PP	Head – Power	MR
05.04.2021	05.04.2021	05.04.2021