0 0	[プログラム名:新規プログラム1] [セクション名:セクション1] センサの電源										
	P On				+	+	101.01	ſ	+	+	+
			+ +		+	+	101.02			+	+
					+	+	101.03			+	+
			+ +		+	+	101.04		+	+	+
					+	+	101.05			+	+
					+	+	101.06			+	+
					+	+	+ 10 <u>1</u> .07			+	+
1	L				+	+	, '' Ö'				
. 8	押しボタン I: 0.02					+	+	r ·			+
	P_Off		+ +		+	+	* CNTR(012) + 0000	・ 可逆カウンタ カウンタ番号		+	+
					+	+	#1		+	+	+
_	<u> </u>							設定値			
2 13	C0000		1 .			+	W1.00				
	W1.00	I: 0.02									
3 18	リセット用光電	センサ			+	+	+	•		*	+
10	I: 0.05	T0003	+ +		+		W2.00		+	+	+
	W2.00	, ri ,			+	+				*	+
4	リセット				+	+				+	+
22	W2.00				+	+	+	·		÷	+
			+ +		+	+	TIM 0003	100ms タイマ (タイ タイマ番号	(4)[BCD]	+	+
						+	#10	設定値		+	+
5					+	+	#10	放在區			+
24	全コンベア運転 W1.00				+	+	* Q: 100.05	r			+
	\vdash						0 $-$				
6 26	W1.00	W3.00	W2.00 W2.00				Q: 100.04				
7 30	W1.00	W4.00	W2.00		*	*	Q: 100.03			*	*
8 34	コンベア2 STC)P			+	+				+	+
- '	W3.00				+	+	TIM	100ms ያイマ (ያብ	* (4)[BCD]	+	*
	. !! .				+	+	0001	タイマ番号		+	+
					+	+	#10	設定値	+	+	+
9	コンベア3STOF				+	+	,	Ļ		+	+
36	W4.00				+	+	+	İ		+	+
			+ +		+	+	TIM -	100ms タイマ (タイ タイマ番号	(4)[BCD]	+	+
							#10	設定値		+	+
10					+	+	#10	D.C.IE			+
38	金属センサ		* T0001 *	I: 0.05	+		* W3.00	r		+	+
	I: 0.04 W3.00		. 1 0001			+	W3.00				+
	W3.00	W1.00									
11 45	コンベア2 shift					*				*	-
	W3.00	W2.00	*		*	· ·	W0.10	·			·
	W0.10				*	+	,		•	*	+
12	W0.10	<u> </u>	+ +		+	+	Q: 100.01			+	+
13	アルミセンサ				+	*	 O			+	
51	I: 0.06		T0002	I: 0.05	+	+	* W4.00	Ť.	+	+	+
	W4.00	W1.00	И	—и—	+	+	. — O —			+	+
14	\vdash	-+-) + +		+	+	+	ļ		+	+
58	コンベア3 shift				+	+	+	r	+	+	+
15	W4.00	W2.00			+	+	* W0.12				
58	W4.00 W0.12	W2.00				+	W0.12				
16 62	W0.12				-	Ť	Q: 100.02				•
17					*	*			•	•	*
18	,				+	+	+			+	+
19											
	1										