



CCN Test Procedure

AD-300 - MHWIRTH (DLS)

Change No:

0006

CCN Title/Identification:

AD 300 hamonization update based on Commissioning findings up to AD 303

Application:

DWCS DV Drawworks Control System - Drillview

Test Description:

Step by Step Procedure:

Step #	Description / What to do	Acceptance criteria / What to look for	Comments	Passed Site/By/Date
1	Update HMI firmware during upload.	Firmware is updated, runtime is loaded.	As long as the HMI time is not set communication towards PLC might not work.	RIG SIM
2	Setup HMI according to description.	Values are indicated correctly, system is setup according to DWCS support document.		RIG SIM
3	Check updated screen DW_Load.	All values are indicated correctly, there is no indication missing or indication of overflow.		RIG SIM ACB 12.02.26
4	Check updated screen DW_AutoDriller.	All values are indicated correctly, there is no indication missing or indication of overflow.		RIG SIM ACB 12.02.26
5	Check updated screen Pop-up_DiscBrakeTrend.	All values are indicated correctly, there is no indication missing or indication of overflow.		RIG SIM ACB 12.02.26
6	Check updated screen Pop-up_AutoDrillerRegulator.	All values are indicated correctly, there is no indication missing or indication of overflow.		RIG SIM ACB 12.02.26
7	Check updated screen Pop-up_AutoDrillerRopTrend.	All values are indicated correctly, there is no indication missing or indication of overflow.		RIG SIM ACB 12.02.26
8	Check updated screen Pop-up_AutoDrillerSppTrend.	All values are indicated correctly, there is no indication missing or indication of overflow.		RIG SIM ACB 12.02.26

Administration / Sign Out:

Test Site	Accepted by Customer	Accepted
RIG	☐	☐
SIM	☐	☒ Yes Achim Braml (ACB) 12.02.2026



CCN Test Procedure

AD-300 - MHWIRTH (DLS)

Change No:

0006

9	Check updated screen Pop-up_AutoDrillerTrqTrend.	All values are indicated correctly, there is no indication missing or indication of overflow.		RIG SIM ACB 12.02.26
10	Check updated screen Pop-up_AutoDrillerWobTrend.	All values are indicated correctly, there is no indication missing or indication of overflow.		RIG SIM ACB 12.02.26
11	Check updated screen Pop-up_HookPositionTrend.	All values are indicated correctly, there is no indication missing or indication of overflow.		RIG SIM ACB 12.02.26
12	Check updated alarm text from diagnostic for VFD and Braking Chopper.	Alarm texts in DWCS HMI fit updated SA06.		RIG SIM ACB 12.02.26
13	Check updated alarm text for lubrication filter.	Alarm texts in DWCS HMI fit updated SA06 and equipment Tag.		RIG SIM ACB 12.02.26
14	Interlock text for reduced motor mode limitation.	Interlock is indicated in DWCS HMI when operating at the limit.		RIG SIM ACB 12.02.26

Test Observations, Comments, etc.:

Administration / Sign Out:

Test Site	Accepted by Customer	Accepted		
RIG	☐	☐		
SIM	☐	☒ Yes	Achim Braml (ACB)	12.02.2026