ORD-3

Giling Computer Applications

Spaxbooster and DDX Booster Revised: March 2, 2012

Revision: 1.2

Qty	Ref	Part	Orde	er nr	Supplier
1	R1 2.2 KOhm ¼ Watt (680 Ohm for USB-RS232 cables)				
	R2,R3		1.8 KOhm ¼ Watt		
	R4		30 KOhm ¼ Watt		
	R5		33 Ohm 5 Watt	5W AXIAL 0,33	Reichelt
	R6		0 KOhm ¼ Watt		
	R8,R9,R12		30 Ohm ¼ Watt		
	R10		00 Ohm 2 Watt	2W DRAHT 100	Reichelt
	R11		70 Ohm ¼ Watt		
	R13		KOhm ¼ Watt		
_	R14		2 KOhm ¼ Watt 1% me	etalfilm	
	R15		680 Ohm ¼ Watt 1% metalfilm		
	R16		560 Ohm ¼ Watt 1% metalfilm		
_	C1	_	20 nF MKT	MKS-2 220N	Reichelt
	C2,C3		5-33 nF MKT	MKS-2 15N	Reichelt
	C4		CO 100 uF 35V radial	RAD 100/35	Reichelt
	C5		CO 1000 uF 25V radial	RAD 1000/25	Reichelt
_	C6,C10		CO 10 uF 16V radial	RAD 10/16	Reichelt
	C9,C11		CO 4.700uF 35V	RAD 4.700/35	Reichelt
	C12		00 nF ceramic	KERKO 100n	Reichelt
_	C13		00 nF MKT	MKS-4 100N	Reichelt
	C14		CO 100uF 16V radial	RAD 100/16	Reichelt
	D1		chottky diode	1N5822 OR SB330	Reichelt
_	D2		IODE 1N4148	1N4148	Reichelt
	LED1,LED3		ED 3mm green	LED B-3 GN	Reichelt
	LED2		ED 3mm red	LED B-3 RT	Reichelt
	VR1		V regulator	7805 TO220	Reichelt
_	VR2		2V regulator	LM2576T-12	Reichelt
_	U1		ower IC	L6203	Reichelt
	U2		IC12F675 + socket	PIC 12F675-I/P	Reichelt
	U3,U4		N137 + socket	6N137	Reichelt
	U5	_	ngle Opto-coupler	PC817	Reichelt
	J1		onnector	AKL230-04+AKL249-	
	St1,St2,St3		J12 connector	MEBP 6-6s	Reichelt
	JP1	3	pin header with jumper		
	SW2		p switch 2-pole		
	GR1		RIDGE 6Amp	KBU6A	Reichelt
_	L1		NDUCTOR 100 uH	FED 100u	Reichelt
1	 F1		JSE 1,85 Amp	PFRA185	Reichelt
1			ooling	V PR127/94-M3	Reichelt
4			ips	MC725	Reichelt
3			crews	M3x8	
4			ounting supports	DA4-10mm	Reichelt
4			crews	M4x8	
1		_	CBoard ORD-3		
1			able RJ12 + SubD9 fema	la.	

Important !!!!!!

For Power IC and Regulators:

First mount cooling device with screws, then insert IC and regulators, bending wires so that they are flat to cooling, then fix clamps to hold IC's and after that solder IC's.