GCA_PI01

Giling Computer Applications Update: 12-oct 2013 In cooperation with Rocrail Update by: Peter Giling

Qty	Reference	Description
2	R1,R2	Resistor 220 Ohm 1/8 Watt
1	R3	Resistor 2.2 Kohm 1/8 Watt
2	R4,R5	Resistor 270 Ohm 1/8 Watt
1	C1	Capacitor 0,1 uF ceramic
1	Led1	Led 3mm green
1	Led2	Led 3mm red
1	IC1	Dil8 Socket
1	JP1	2 pin header + jumper
1	PB1	pushbutton
1	S1	PSS254/4G
1	J1	RJ12 or RJ45 socket
1	PI1	female header 13x2
1	IC1	P82B715
1	Pc-board	GCA_Pi01

Assemble all parts according the following order of this list!

Please remark that J1 and Pl1 are located on bottom side!

Bottom side is without sikscreen.

Before assembling, 2 holes of 3.2 mm should be drilled, either on

Pos A when RJ45 connectors are to be installed OR

Pos B when RJ12 connectors are used.

Alle Teile in oben angegeben Folgenreihe montieren.

Bitte Achtung das J1 und PI1 an Untenseite der Platine montiert werden.

Untenseite ist ohne Aufdruck.

2 Löcher ,32 mm sollen gedrillt werden vor montage der Teile

Für RJ45 Buchse Löcher drillen in Pos A

Für RJ12 Buchse Löcher drillen in Pos B