



Run Chart




Histogram of x – target



Tolerance View



Process Capability using normal distribution for datos



$$C_{pkU} = 1.07$$

$$C_{pkL} = 0.9$$

$$C_{pk} = 0.9$$

$$C_p = 0.99$$


$$n = 20$$

$$A = 0.572$$

$$p = 0.119$$

$$\text{mean} = 19.7$$

$$\text{sd} = 1.01$$



Expected Fraction Nonconforming

$$p_U = 0.000672055$$

$$\text{ppm} = 672.055$$

$$p_L = 0.00334503$$

$$\text{ppm} = 3345.03$$

$$p_t = 0.00401708$$

$$\text{ppm} = 4017.08$$


Observed

$$\text{ppm} = 0$$

$$\text{ppm} = 0$$

$$\text{ppm} = 0$$

Process Capability using weibull distribution for weib



$$C_{pkU} = 1.07$$

$$C_{pkL} =$$

$$C_{pk} = 1.07$$

$$C_{pkL} =$$


$$n = 20$$

$$A = 0.418$$

$$p < 0.25$$

$$\text{shape} = 2.29$$

$$\text{scale} = 8.38$$



Expected Fraction Nonconforming

$$p_U = 0.000656078$$

$$\text{ppm} = 656.078$$

$$p_L = 0$$

$$\text{ppm} = 0$$

$$p_t = 0.000656078$$

$$\text{ppm} = 656.078$$


Observed

$$\text{ppm} = 0$$


$$\text{ppm} = 0$$

$$\text{ppm} = 0$$


Components of Variation




Measurement by Part




Measurement by Operator



$\bar{x}$ Chart



Interaction Operator: Part



R Chart

