

Force sensor



You can use this force sensor as an input device (button) or to sense the presence of a small object.

The 1106 pin reads 0V when no force is applied. If a force is applied on the button, the current value increases up to 5V. The analog output of voltage is connected to a PC through USB port.

This simple sensor is not accurate enough to be used as a proper scale and cannot support constant force over time.

Here you can find more information about it.







eCraft2Learn H2020-731345 - UEF.

This work is licensed under a License Creative Commons Atribution 4.0 International.

This project has received funding from the European Union's Horizon 2020 Coordination & Research and Innovation Action Under Grant Agreement No 731345.