

CONTENTS

What's in this catalog

Voltages are shown for each model: 1Ph 230V runs off a normal plug, 3Ph 380V needs three-phase power. The welding generators need no power at all. Tell us the job and your power supply and we will match the machine.

Stick (MMA) welders	04–06
MIG welders	07–10
TIG welders	11–13
Plasma cutters	14–15
Stud welders	16
Submerged-arc and spot welders	17
Laser welders	18
Welding generators	19
Battery chargers	20
Air compressors	21