Field Revisit Report

SITE-0231

Site	SITE-0231
Visit Date	2026-10-20
Inspector	Ya-Fang Hsu

Revisit Findings

Item	Result
F-1001	F-1001 (Handrail broken): resolved — handrail refastened and passed the wobble test
F-1050	New finding F-1050 (Cracked pavement near entrance): roughly 1.2 m of cracked pavement near the entrance, a trip hazard, to be rechecked by 2026-11-19