ahds@engineer.com Email:

STM32CubeIDE 2.2.0

POCKET REFERENCE · KEYBOARD SHORTCUTS

Quick STM32 reference · Windows · Eclipse Default key scheme.

01 · Quick start

Ctrl + **Shift** + **L**	Show available shortcuts; open Keys preferences.
Ctrl + **B**	Build All: build projects in the Workspace.
F11	Debug: start debugging with the current configuration.
Ctrl + **Space**	Content Assist: complete functions, variables and parameters.
Ctrl + **Shift** + **R**	Open Resource: quickly locate a project file.
Ctrl + **Shift** + **F**	Format: format the selection or current document.

i Default (Eclipse) key scheme on Windows; the active context can change commands.

02 · Files and editor

Ctrl + **S**	Save the current file.
Ctrl + **Shift** + **S**	Save All modified files; confirm assignment under Keys.
Ctrl + **F4**	Close the current editor.
Ctrl + **Shift** + **F4**	Close All editors.
Ctrl + **F**	Find / Replace in the current file.
Ctrl + **M**	Maximize Active View or Editor; toggle back.

© AHDS. Portfolio / educational material. Redistribution or reproduction without permission is not authorized.

F12	Activate Editor and place focus in the editor.
Ctrl + E	Switch Editor: list open files.
Ctrl + Page Up / Down	Move between editor tabs.

03 · C/C++ navigation

Ctrl + O	Quick Outline: browse functions and symbols.
Ctrl + L	Go to Line by number.
Ctrl + H	Search across a project or Workspace.
Ctrl + Shift + T	Open Element: locate a symbol.
Alt + Left / Right	Backward / Forward History: navigate visited locations.
Ctrl + Q	Last Edit Location: return to the last change.
Ctrl + Alt + H	Call Hierarchy: inspect callers of a function.
Ctrl + Alt + I	Include Browser: inspect #include dependencies.
Alt + Enter	Properties of the selected resource.

04 · Editing and formatting

Ctrl + I	Indent the line or selected text.
Shift + Alt + A	Toggle Block Selection (rectangular selection).
Shift + Alt + R	Rename / Refactor a C/C++ symbol.
Ctrl + + / Ctrl + -	Zoom In / Zoom Out editor text.
Ctrl + Shift + /	Add Block Comment in the C/C++ editor.
Ctrl + Shift + N	Add Include directive in the C/C++ editor.

© AHDS. Portfolio / educational material. Redistribution or reproduction without permission is not authorized.

i Some mappings depend on keyboard layout and C/C++ editor context.

05 · Debug

F5	Step Into a called function.
F6	Step Over a call without entering it.
F7	Step Return from the current function.
F8	Resume execution until the next Breakpoint.
Ctrl + **R**	Run to Line in Debug context.
Ctrl + **F2**	Terminate the debug session.
Ctrl + **Alt** + **B**	Skip Breakpoints temporarily.

i Reverse debugging requires a compatible Debug Backend.

06 · Build, CubeMX and settings

Shift + **F9**	Build Target Build when supported by the active context.
Window > **Preferences** > **General** > **Keys**	View, search and customize keyboard shortcuts.
Ctrl + **Shift** + **L**	Check assignments in your installed release.

i The CubeMX .ioc GUI has no universal shortcut for every peripheral setting.

i A successful Build does not automatically mean firmware was flashed to the MCU.

07 · Daily workflow

1 · Ctrl + **Shift** + **R**	Open main.c or another project resource.

© AHDS. Portfolio / educational material. Redistribution or reproduction without permission is not authorized.

2 · Ctrl + Space	Use HAL function suggestions.
3 · Ctrl + S	Save changes.
4 · Ctrl + B	Build and inspect Problems / Console.
5 · F11	Start ST-LINK Debug.
6 · F6 / F5 / F8	Step over, step into, or resume.
7 · Ctrl + F2	End the Debug session.

Sources and verification

ST UM2609 — STM32CubeIDE User Guide; ST STM32CubeProgrammer 2.23 documentation.
https://www.st.com/en/development-tools/stm32cubeide.html
https://www.st.com/en/development-tools/stm32cubeprog.html

© AHDS. Portfolio / educational material. Redistribution or reproduction without permission is not authorized.