


(a) Sampling-zero ringing wear ($\zeta = 0.4$, $t_{\text{ring}} = 14.7$ s)



(b) Command alternates as $z_0 \rightarrow -1$

