

Revision item

Added as a countermeasure for problems during initial flow

Mountains

20160810

Added BDV inspection for coil wire

 \triangle 1

No.