

Probuse Consulting Service Pvt Ltd SAKAR IX, Beside Old Reserve Bank of India, Near City Gold, Ashram Rd Ahmedabad 380009 Gujarat GJ India

TICK-00010 - Machine Engine Fault [New]

Assigned To	Nicole Ford	Customer	Azure Interior
Email	azure.Interior24@example.com	Phone	(870)-931-0505
Company	Probuse Consulting Service Pvt Ltd		

Support Team	Repair Team	Team Leader	Mitchell John
Department	Support	Analytic Account	Machine X5544LK
Project	Machine X5544LK	Priority	High

Create Date	05/14/2019 12:58:22	Close Date	
Is Ticket Closed ?		Total Hours Spent	00:00

Solution

The cooling system doesn't just consist of coolant but a mixture of coolant. anti-freeze and water. The ratio is very important to each engine. The mixture should approximately be 50% water and 44% antifreeze and 6% coolant conditioner.

Minimum antifreeze levels for Caterpillar engines must consist of at least 30% ethylene glycol based antifreeze. Coolant is very alkaline and coolant conditioner helps neutralizes the coolant from deteriorating the engine. It protects the stems. bearings. etc...

The coolant conditioner stabilizes the cooling system and is very important. Make sure to flush the engine before adding any new coolant product or conditioner to the engine.

Solution Image 1



Solution Image 2



Probuse Consulting Service Pvt Ltd SAKAR IX, Beside Old Reserve Bank of India, Near City Gold, Ashram Rd Ahmedabad 380009 Gujarat GJ India



Solution Image 3



Solution Image 4



Solution Image 5



Probuse Consulting Service Pvt Ltd SAKAR IX, Beside Old Reserve Bank of India, Near City Gold, Ashram Rd Ahmedabad 380009 Gujarat GJ India



Description