

# NovaChem Chemicals Pvt. Ltd.

## NovaChem Industrial Plant

Plot No. 18, GIDC Industrial Estate,  
Vadodara, Gujarat - 390010

### Instrument Calibration Report

#### Document Information

|                 |                   |
|-----------------|-------------------|
| Document UUID   | 57FA40D2          |
| Document Number | CAL_EVT-057       |
| Event ID        | EVT-057           |
| Chain ID        | CH-019            |
| Equipment ID    | CV-101            |
| Department      | Inspection        |
| Generated On    | 15-Jul-2026 14:12 |
| Confidentiality | Internal Use Only |

#### Document Control

|                 |              |
|-----------------|--------------|
| Document Number | CAL_EVT-057  |
| Issue Date      | 23-Jun-2026  |
| Revision        | Rev-1.0      |
| Prepared By     | Neha Singh   |
| Approved By     | Anjali Desai |
| Status          | Approved     |

#### Calibration Information

|                     |               |
|---------------------|---------------|
| Calibration Number  | CAL_-057      |
| Event ID            | EVT-057       |
| Equipment ID        | CV-101        |
| Instrument Name     | Control Valve |
| Department          | Inspection    |
| Assigned Technician | Neha Singh    |
| Status              | Closed        |

#### Equipment Details

|                |               |
|----------------|---------------|
| Equipment ID   | CV-101        |
| Equipment Name | Control Valve |
| Area           | Reactor Area  |

|                   |                 |
|-------------------|-----------------|
| Department        | Inspection      |
| Shift             | Night           |
| Reported From     | Tank Farm       |
| Asset Criticality | High            |
| Failure Category  | Instrumentation |
| Downtime          | 2 Hours         |

Calibration Objective

Calibration check performed for:

CV-101

Purpose was to verify instrument accuracy and detect measurement deviation.

Calibration Findings

Calibration findings:

Equipment:

Control Valve

Observed Condition:

Routine PM

Deviation Analysis

Calibration deviation identified.

Possible Cause:

Routine schedule

Adjustment Performed

Adjustment performed.

Corrective Action:

Serviced

Calibration Verification

Post-adjustment verification completed.

Instrument accuracy restored successfully.

Previous Equipment History

| Event   | Date       | Failure          | Status |
|---------|------------|------------------|--------|
| EVT-027 | 2026-03-25 | Scheduled        | Closed |
| EVT-042 | 2026-05-09 | Bearing wear     | Closed |
| EVT-057 | 2026-06-23 | Routine schedule | Closed |

Calibration Checklist

- ☒ Lock Out / Tag Out (LOTO) Followed
- ☒ PPE Worn
- ☒ Visual Inspection Completed
- ☒ Lubrication Checked
- ☒ Leak Inspection Completed
- ☒ Alignment Verified
- ☒ Trial Run Successful

Recommendations

Continue weekly inspection.

## Linked Documents

- WO\_EVT-057.docx
- MNT\_EVT-057.docx
- INS\_EVT-057.docx
- EMAIL\_EVT-057.txt

## Approval

|             |              |
|-------------|--------------|
| Prepared By | Neha Singh   |
| Approved By | Anjali Desai |