

# NovaChem Chemicals Pvt. Ltd.

## NovaChem Industrial Plant

Plot No. 18, GIDC Industrial Estate,  
Vadodara, Gujarat - 390010

### Operational Incident Report

#### Document Information

|                 |                   |
|-----------------|-------------------|
| Document UUID   | 4AC2C59A          |
| Document Number | INC_EVT-022       |
| Event ID        | EVT-022           |
| Chain ID        | CH-008            |
| Equipment ID    | CT-101            |
| Department      | Engineering       |
| Generated On    | 15-Jul-2026 13:06 |
| Confidentiality | Internal Use Only |

#### Document Control

|                 |              |
|-----------------|--------------|
| Document Number | INC_EVT-022  |
| Issue Date      | 10-Mar-2026  |
| Revision        | Rev-1.0      |
| Prepared By     | Rahul Sharma |
| Approved By     | Amit Verma   |
| Status          | Approved     |

#### Incident Information

|                 |                |
|-----------------|----------------|
| Incident Number | INC_-022       |
| Event ID        | EVT-022        |
| Date            | 2026-03-10     |
| Department      | Engineering    |
| Area            | Utility        |
| Shift           | Morning        |
| Reported By     | Utilities Area |
| Status          | Closed         |

#### Equipment Details

|                |               |
|----------------|---------------|
| Equipment ID   | CT-101        |
| Equipment Name | Cooling Tower |

|                   |                 |
|-------------------|-----------------|
| Area              | Utility         |
| Department        | Engineering     |
| Shift             | Morning         |
| Reported From     | Utilities Area  |
| Asset Criticality | Medium          |
| Failure Category  | Instrumentation |
| Downtime          | 6 Hours         |

Incident Description

During routine plant operation an incident occurred involving equipment

CT-101

Issue Reported:

Minor spill

Impact Assessment

|                   |         |
|-------------------|---------|
| Severity          | High    |
| Priority          | Low     |
| Downtime          | 6 Hours |
| Asset Criticality | Medium  |

Root Cause Analysis

Failure Category:

Instrumentation

Root Cause:

Loose flange

Immediate Action Taken

Operations team responded immediately.

Corrective Action:

Flange tightened

Safety Classification

|                    |                 |
|--------------------|-----------------|
| Failure Category   | Instrumentation |
| Severity           | High            |
| Follow-up Required | No              |

Safety Requirements

Gas detector readings were within permissible limits.

Recommendations

Conduct thermography inspection next month.

Previous Equipment History

| Event   | Date       | Failure      | Status |
|---------|------------|--------------|--------|
| EVT-022 | 2026-03-10 | Loose flange | Closed |

Linked Documents

- WO\_EVT-022.docx
- MNT\_EVT-022.docx
- INS\_EVT-022.docx
- EMAIL\_EVT-022.txt

Approval

|             |              |
|-------------|--------------|
| Prepared By | Rahul Sharma |
| Approved By | Amit Verma   |