

# NovaChem Chemicals Pvt. Ltd.

## NovaChem Industrial Plant

Plot No. 18, GIDC Industrial Estate,  
Vadodara, Gujarat - 390010

### Operational Incident Report

#### Document Information

|                 |                   |
|-----------------|-------------------|
| Document UUID   | E507C20D          |
| Document Number | INC_EVT-031       |
| Event ID        | EVT-031           |
| Chain ID        | CH-011            |
| Equipment ID    | P-101             |
| Department      | Inspection        |
| Generated On    | 15-Jul-2026 13:06 |
| Confidentiality | Internal Use Only |

#### Document Control

|                 |              |
|-----------------|--------------|
| Document Number | INC_EVT-031  |
| Issue Date      | 06-Apr-2026  |
| Revision        | Rev-1.0      |
| Prepared By     | Suresh Kumar |
| Approved By     | Anjali Desai |
| Status          | Approved     |

#### Incident Information

|                 |                |
|-----------------|----------------|
| Incident Number | INC_-031       |
| Event ID        | EVT-031        |
| Date            | 2026-04-06     |
| Department      | Inspection     |
| Area            | Tank Farm      |
| Shift           | Morning        |
| Reported By     | Utilities Area |
| Status          | Closed         |

#### Equipment Details

|                |           |
|----------------|-----------|
| Equipment ID   | P-101     |
| Equipment Name | Feed Pump |

|                   |                 |
|-------------------|-----------------|
| Area              | Tank Farm       |
| Department        | Inspection      |
| Shift             | Morning         |
| Reported From     | Utilities Area  |
| Asset Criticality | High            |
| Failure Category  | Instrumentation |
| Downtime          | 2 Hours         |

Incident Description

During routine plant operation an incident occurred involving equipment

P-101

Issue Reported:

Emergency drill

Impact Assessment

|                   |         |
|-------------------|---------|
| Severity          | High    |
| Priority          | Low     |
| Downtime          | 2 Hours |
| Asset Criticality | High    |

Root Cause Analysis

Failure Category:

Instrumentation

Root Cause:

Scheduled

Immediate Action Taken

Operations team responded immediately.

Corrective Action:

Training

Safety Classification

|                    |                 |
|--------------------|-----------------|
| Failure Category   | Instrumentation |
| Severity           | High            |
| Follow-up Required | No              |

Safety Requirements

Gas detector readings were within permissible limits.

Recommendations

Increase preventive maintenance frequency.

Previous Equipment History

| Event   | Date       | Failure      | Status |
|---------|------------|--------------|--------|
| EVT-001 | 2026-01-06 | Bearing wear | Closed |
| EVT-002 | 2026-01-09 | Follow-up    | Closed |
| EVT-003 | 2026-01-12 | Routine PM   | Closed |
| EVT-004 | 2026-01-15 | Seal wear    | Closed |
| EVT-005 | 2026-01-18 | Follow-up    | Closed |
| EVT-016 | 2026-02-20 | Seal failure | Closed |
| EVT-031 | 2026-04-06 | Scheduled    | Closed |

Linked Documents

- EMAIL\_EVT-031.txt

Approval

|             |              |
|-------------|--------------|
| Prepared By | Suresh Kumar |
| Approved By | Anjali Desai |