

# NovaChem Chemicals Pvt. Ltd.

## NovaChem Industrial Plant

Plot No. 18, GIDC Industrial Estate,  
Vadodara, Gujarat - 390010

### Equipment Incident Report

#### Document Information

|                 |                   |
|-----------------|-------------------|
| Document UUID   | C46F7E40          |
| Document Number | INC_EVT-061       |
| Event ID        | EVT-061           |
| Chain ID        | CH-021            |
| Equipment ID    | P-101             |
| Department      | Safety            |
| Generated On    | 15-Jul-2026 13:06 |
| Confidentiality | Internal Use Only |

#### Document Control

|                 |             |
|-----------------|-------------|
| Document Number | INC_EVT-061 |
| Issue Date      | 05-Jul-2026 |
| Revision        | Rev-1.0     |
| Prepared By     | Pooja Mehta |
| Approved By     | Karan Gupta |
| Status          | Approved    |

#### Incident Information

|                 |                |
|-----------------|----------------|
| Incident Number | INC_-061       |
| Event ID        | EVT-061        |
| Date            | 2026-07-05     |
| Department      | Safety         |
| Area            | Tank Farm      |
| Shift           | Morning        |
| Reported By     | Field Operator |
| Status          | Closed         |

#### Equipment Details

|                |           |
|----------------|-----------|
| Equipment ID   | P-101     |
| Equipment Name | Feed Pump |

|                   |                 |
|-------------------|-----------------|
| Area              | Tank Farm       |
| Department        | Safety          |
| Shift             | Morning         |
| Reported From     | Field Operator  |
| Asset Criticality | High            |
| Failure Category  | Instrumentation |
| Downtime          | 3 Hours         |

Incident Description

An incident was reported involving

Feed Pump

Description:

Instrument calibration

Impact Assessment

|                   |         |
|-------------------|---------|
| Severity          | Low     |
| Priority          | Medium  |
| Downtime          | 3 Hours |
| Asset Criticality | High    |

Root Cause Analysis

Initial investigation indicates:

Routine

Immediate Action Taken

Immediate corrective action taken:

Calibrated

### Safety Classification

|                    |                 |
|--------------------|-----------------|
| Failure Category   | Instrumentation |
| Severity           | Low             |
| Follow-up Required | No              |

### Safety Requirements

Area was barricaded before maintenance work.

### Recommendations

Perform vibration analysis after one week.

### Previous Equipment History

| Event   | Date       | Failure      | Status |
|---------|------------|--------------|--------|
| EVT-001 | 2026-01-06 | Bearing wear | Closed |
| EVT-002 | 2026-01-09 | Follow-up    | Closed |
| EVT-003 | 2026-01-12 | Routine PM   | Closed |
| EVT-004 | 2026-01-15 | Seal wear    | Closed |
| EVT-005 | 2026-01-18 | Follow-up    | Closed |
| EVT-016 | 2026-02-20 | Seal failure | Closed |
| EVT-031 | 2026-04-06 | Scheduled    | Closed |
| EVT-046 | 2026-05-21 | Loose flange | Closed |
| EVT-061 | 2026-07-05 | Routine      | Closed |

### Linked Documents

- WO\_EVT-061.docx
- MNT\_EVT-061.docx
- INS\_EVT-061.docx
- EMAIL\_EVT-061.txt

### Approval

|             |             |
|-------------|-------------|
| Prepared By | Pooja Mehta |
| Approved By | Karan Gupta |