

# NovaChem Chemicals Pvt. Ltd.

## NovaChem Industrial Plant

Plot No. 18, GIDC Industrial Estate,  
Vadodara, Gujarat - 390010

### Safety Incident Investigation

#### Document Information

|                 |                   |
|-----------------|-------------------|
| Document UUID   | 49E59007          |
| Document Number | SAF_EVT-024       |
| Event ID        | EVT-024           |
| Chain ID        | CH-008            |
| Equipment ID    | T-101             |
| Department      | Operations        |
| Generated On    | 15-Jul-2026 14:01 |
| Confidentiality | Internal Use Only |

#### Document Control

|                 |             |
|-----------------|-------------|
| Document Number | SAF_EVT-024 |
| Issue Date      | 16-Mar-2026 |
| Revision        | Rev-1.0     |
| Prepared By     | Neha Singh  |
| Approved By     | Arun Nair   |
| Status          | Approved    |

#### Safety Information

|                      |              |
|----------------------|--------------|
| Safety Report Number | SAF_-024     |
| Event ID             | EVT-024      |
| Department           | Operations   |
| Area                 | Tank Farm    |
| Shift                | Night        |
| Reported By          | Boiler House |
| Severity             | High         |
| Status               | Closed       |

#### Equipment Details

|                |                   |
|----------------|-------------------|
| Equipment ID   | T-101             |
| Equipment Name | Raw Material Tank |

|                   |              |
|-------------------|--------------|
| Area              | Tank Farm    |
| Department        | Operations   |
| Shift             | Night        |
| Reported From     | Boiler House |
| Asset Criticality | High         |
| Failure Category  | Mechanical   |
| Downtime          | 6 Hours      |

Safety Event Description

Safety incident occurred during:

Night shift.

Incident Details:

Leakage detected

Hazard Identification

Hazard category:

Mechanical

Root Cause:

Seal failure

Risk Assessment

Risk Priority:

High

Severity:

High

## Immediate Action Taken

Immediate corrective action:

Seal replaced

## Root Cause Analysis

Seal failure

## Corrective Action

Seal replaced

## Preventive Action

Provide safety awareness training  
and improve preventive monitoring.

## Safety Officer Remarks

Preventive maintenance interval should be reduced.

## Safety Compliance Checklist

☒ Lock Out / Tag Out (LOTO) Followed

☒ PPE Worn

☒ Visual Inspection Completed

☒ Lubrication Checked

☒ Leak Inspection Completed

☒ Alignment Verified

☒ Trial Run Successful

Previous Equipment History

| Event   | Date       | Failure      | Status |
|---------|------------|--------------|--------|
| EVT-024 | 2026-03-16 | Seal failure | Closed |

Recommendations

Check lubrication schedule.

Linked Documents

- WO\_EVT-024.docx
- MNT\_EVT-024.docx
- INS\_EVT-024.docx
- EMAIL\_EVT-024.txt

Approval

|             |            |
|-------------|------------|
| Prepared By | Neha Singh |
| Approved By | Arun Nair  |