

# NovaChem Chemicals Pvt. Ltd.

## NovaChem Industrial Plant

Plot No. 18, GIDC Industrial Estate,  
Vadodara, Gujarat - 390010

### Safety Incident Investigation

#### Document Information

|                 |                   |
|-----------------|-------------------|
| Document UUID   | 547BB405          |
| Document Number | SAF_EVT-060       |
| Event ID        | EVT-060           |
| Chain ID        | CH-020            |
| Equipment ID    | V-101             |
| Department      | Quality           |
| Generated On    | 15-Jul-2026 14:01 |
| Confidentiality | Internal Use Only |

#### Document Control

|                 |             |
|-----------------|-------------|
| Document Number | SAF_EVT-060 |
| Issue Date      | 02-Jul-2026 |
| Revision        | Rev-1.0     |
| Prepared By     | Priya Patel |
| Approved By     | Neha Singh  |
| Status          | Approved    |

#### Safety Information

|                      |              |
|----------------------|--------------|
| Safety Report Number | SAF_-060     |
| Event ID             | EVT-060      |
| Department           | Quality      |
| Area                 | Reactor Area |
| Shift                | Night        |
| Reported By          | CCR          |
| Severity             | Medium       |
| Status               | Closed       |

#### Equipment Details

|                |              |
|----------------|--------------|
| Equipment ID   | V-101        |
| Equipment Name | Relief Valve |

|                   |                 |
|-------------------|-----------------|
| Area              | Reactor Area    |
| Department        | Quality         |
| Shift             | Night           |
| Reported From     | CCR             |
| Asset Criticality | Critical        |
| Failure Category  | Instrumentation |
| Downtime          | 0 Hours         |

Safety Event Description

Safety incident occurred during:

Night shift.

Incident Details:

Parameter deviation

Hazard Identification

Hazard category:

Instrumentation

Root Cause:

Calibration drift

Risk Assessment

Risk Priority:

Medium

Severity:

Medium

## Immediate Action Taken

Immediate corrective action:

Recalibrated

## Root Cause Analysis

Calibration drift

## Corrective Action

Recalibrated

## Preventive Action

Provide safety awareness training  
and improve preventive monitoring.

## Safety Officer Remarks

No abnormal noise observed after trial run.

## Safety Compliance Checklist

☒ Lock Out / Tag Out (LOTO) Followed

☒ PPE Worn

☒ Visual Inspection Completed

☒ Lubrication Checked

☒ Leak Inspection Completed

☒ Alignment Verified

☒ Trial Run Successful

### Previous Equipment History

| Event   | Date       | Failure           | Status |
|---------|------------|-------------------|--------|
| EVT-030 | 2026-04-03 | Loose flange      | Closed |
| EVT-045 | 2026-05-18 | Routine           | Closed |
| EVT-060 | 2026-07-02 | Calibration drift | Closed |

### Recommendations

Monitor bearing temperature daily.

### Linked Documents

- EMAIL\_EVT-060.txt

### Approval

|             |             |
|-------------|-------------|
| Prepared By | Priya Patel |
| Approved By | Neha Singh  |