USERS MANUAL

Prerequisites:

1. Plug adapter for power supply, user can use 9 volt as well as 12 volt DC adapter. Minimum current requirement is 1 Amps
2. Camera must be connected via USB port. You can find USB port at the back of the machine.
3. After plugging DC adapter turn on the switch at the back.

Direction:

1. " Welcome remove any object.." when this text appears on lcd, user can proceed.
2. If appears "failed to fetch crop info" it states that fetching any update from database was unsuccessful. If you want to get updates then check connection or press "B".
3. "place your object…." Do as written on screen of weighing machine.
4. Place item on weighing panel.
5. If user wants to tare the weight then press "D".
6. Press "*" to enter CROP ID.
7. Enter CROP ID, then press "*" to conform.
8. Enter TROUGH ID, then press "*" to confirm.
9. Enter LOCATION ID, then press "*" to confirm.
10. If mistyped then use "#" button to backspace.
11. If appears "Failed no camera attached" then check camera connection properly.
12. "successful" states that your data have been stored in database.

 If something went wrong!!

1. Press button "B" for restart script.
2. Press button "C" for restart.

Shutdown:

Press button "A" to shutdown the system.