


Spider 1.0 + BTT 2209 – Voron 2.4 build





18. Endstop X

19. Endstop Y

21. Endstop Z


20. Probe

- Raspberry
- **Hotend Heater**
- 10. SSR
- 11. 24V to SSR
- 12. 24V Power

Supply and RasPi


- 13. Hotend Fan
- 14. Part Cooling Fan
- 15. Case Fan
- 16. Thermistor Hotend
- 17. Thermistor Bed


- **B-Motor**
- 2. A-Motor
- ZO Stepper Front Left
- Extruder
- Z1 Stepper Rear Left
- Z2 Stepper Rear Right
- 7. Z3 Stepper Front Right




Bridging Z2-Mot

It is hard to see but Jumpers need to be placed in the JST connector.





Jumper for TMC 2209 (also BTT)





E4-Mot

V2 with the printer.cfg from FYSETC GitHub do not need E4-Mot.

So no Stepper driver needed.

