Shop PPE Matrix

Shop PPE Matrix (SOP-PPE-02)

Document type: safety

Minimum PPE (all production areas)
- Safety glasses with side shields
- Steel-toe boots
- Hearing protection in marked zones (>85 dBA)

Task-Specific PPE
Task	Extra PPE
Bearing / spindle service	Cut-resistant gloves, face shield when pressing
Welding	Auto-darkening helmet, FR clothing, welding gloves
Chemical handling (coolant concentrate)	Chemical gloves, apron, splash goggles
Robot cell entry	High-visibility vest, teach-pendant tether

Notes
Damaged PPE must be replaced immediately from the crib. Prescription safety glasses are av
ailable via EHS.