

# P-101 Inspection Report

## Document Information

Document ID: INS-P101-001  
Equipment: Pump P-101  
Inspection Date: 06 September 2026  
Inspector: Maintenance Inspection Team  
Location: Unit A

## Inspection Summary

Pump P-101 was inspected during normal operation. Abnormal vibration was observed around the bearing housing.

Observed vibration: 8.2 mm/s RMS. Reference threshold used for this demonstration: 7.1 mm/s RMS.

Bearing observation: abnormal noise and increased vibration near the drive-end bearing.

Temperature at bearing housing: 76°C.

Equipment status: Operating, but maintenance inspection is recommended.

## Findings

Finding 1: Vibration exceeds the demonstration threshold of 7.1 mm/s.

Finding 2: Audible bearing noise was observed.

Finding 3: No visible external leakage was observed during this inspection.

Probable cause for investigation: bearing degradation.

## Recommendation

Perform a detailed bearing inspection and review recent maintenance history. Do not treat this report as authorization for automatic shutdown.

## Asset Relationships

Pump P-101 is driven by Motor M-101 and monitored by Sensor S-101. It is connected to Pipeline L-204.