

P-101 Maintenance History

Document Information

Document ID: MNT-P101-001

Equipment: Pump P-101

System: Demonstration Maintenance Records

Recent History

15 July 2026 — Preventive inspection completed. No major defect recorded.

18 August 2026 — Bearing lubrication performed on the drive-end assembly.

28 August 2026 — Operator noted a small increase in vibration compared with the previous observation.

06 September 2026 — Inspection recorded 8.2 mm/s vibration and abnormal bearing noise.

Maintenance Interpretation

The upward vibration trend and recent bearing-related maintenance make the bearing assembly relevant for further investigation. This history alone does not prove the root cause.

Related Assets

Pump: P-101

Motor: M-101

Vibration Sensor: S-101