

APEX-AI

INDUSTRIAL DIAGNOSTIC REPORT

Equipment	P101
Issue	Abnormal vibration
Observed value	8.2 mm/s RMS
Threshold	7.1 mm/s RMS
Probable cause	Bearing degradation for investigation
Risk	HIGH
Recommendation	Perform a detailed bearing inspection and review maintenance history
Approval status	HUMAN_APPROVAL_REQUIRED
Document ID	Not provided
Audit ID	AUD-P101-DEMO
Generated	2026-09-07T09:36:46.053837+00:00

Evidence

- 03_P101_Maintenance_History.pdf - Page 1
- 04_P101_SOP.pdf - Page 1
- 02_P101_Equipment_Manual.pdf - Page 1
- 01_P101_Inspection_Report.pdf - Page 1
- 06_Vibration_Guidelines.pdf - Page 1

Related assets

- P-101 --DRIVEN_BY--> M-101
- P-101 --MONITORED_BY--> S-101
- P-101 --CONNECTED_TO--> L-204

Validation

- [OK] Numerical validation: PASS
- [OK] Source verification: PASS
- [OK] Safety rule validation: PASS