



ESD PCB Bonus Report

Team Smart Dustbin


Schematic





ERC




PCB Editor (Layout)



DRC Constraints



DRC



There were 2 DRC errors. They occurred because pin headers were placed in place of the servo motors, ultrasonic sensor and the RPi 4B, and DRC deemed it erroneous for pin headers to be directly shorted as it claimed that labels with the same net were being shorted. Hence the 2 errors were inevitable.